



Byron 2 2Q/2006 Performance Summary



Performance Indicators

Unplanned Sorams (G)	Safety System Functional Failures (G)	Reactor Coolant System Activity (G)	Drill/Exercise Performance (G)	Occupational Exposure Control Effectiveness (G)	RETS/ODCM Radiological Effluent (G)
Sorams With Loss of Normal Heat Removal (G)	Emergency AC Power System (G)	Reactor Coolant System Leakage (G)	ERO Drill Participation (G)		
Unplanned Power Changes (G)	High Pressure Injection System (G)		Alert and Notification System (G)		
	Heat Removal System (W)				
	Residual Heat Removal System (G)				
	Cooling Water Systems (G)				

Last Modified: August 2, 2006



Most Significant Inspection Findings

2Q/2006	No findings this quarter	No findings this quarter	No findings this quarter	No findings this quarter	No findings this quarter	No findings this quarter
1Q/2006	No findings this quarter	G	G	No findings this quarter	No findings this quarter	No findings this quarter
4Q/2005	G	G	No findings this quarter	No findings this quarter	No findings this quarter	No findings this quarter
3Q/2005	No findings this quarter	G	G	No findings this quarter	No findings this quarter	No findings this quarter

Miscellaneous findings

Additional Inspection & Assessment Information

◆ **Assessment Reports/Inspection Plans:**

- 2Q/2006
- 1Q/2006
- 4Q/2005
- 3Q/2005

◆ **Cross Reference Of Assessment Reports**

◆ **List of Inspection Reports**

- ◆ **List of Assessment Letters/Inspection Plans**
- ◆ **Baseline Inspection Completion Information**

Last Modified: August 25, 2006