
 National Transportation Safety Board PRELIMINARY REPORT AVIATION		NTSB ID: ERA09WA037		Most Critical Injury:		
		Occurrence Date: 11/01/2008		Investigated By: Foreign		
		Occurrence Type: Accident				
Location/Time						
Nearest City/Place Timehri		State	Zip Code	Local Time 1654	Time Zone UTC	
Aircraft Information						
Registration Number N87V		Aircraft Manufacturer BEECH		Model/Series Number 65A90/1		
Type of Aircraft: Airplane			Amateur Built Aircraft? No			
Injury Summary:		Fatal 3	Serious	Minor	None	
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No			
Narrative						
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:						
<p>On November 1, 2008, at about 1654 universal coordinated time, a Beechcraft King Air 65-A90, N87V, owned and operated by Dynamic AvLease incorporated, was reported missing when it did not return from a geological surveying mission in a remote area of Guyana. The airline transport-rated pilot, commercial-rated co-pilot, and passenger are missing. The flight originated from the Cheddi Jagan International Airport, Georgetown, Guyana, earlier that day.</p> <p>According to the aircraft operator, about six aircraft were used to search the area for the missing airplane on November 2, 2008. For two weeks the air search continued and the airplane was not located. The Guyanese Government has called off the air search, and the ground search is ongoing.</p> <p>The accident investigation is under the jurisdiction of the Government of Guyana. Any further information pertaining to this accident may be obtained from:</p> <p>Zulficar Mohamed Head of the Guyana Civil Aviation Authority Phone: 592-624-0586</p> <p>This report is for information purposes only and contains only information released by the Government of Guyana.</p>						
PRELIMINARY INFORMATION - SUBJECT TO CHANGE						

 <p>National Transportation Safety Board PRELIMINARY REPORT AVIATION</p>	NTSB ID: ERA09WA037	
	Occurrence Date: 11/01/2008	
	Occurrence Type: Accident	

Other Aircraft Involved		
Registration Number	Aircraft Manufacturer	Model/Series Number

Accident Information	
Aircraft Damage: None	Accident Occurred During:

Crew	Name	Certificate No.	Injury
Pilot	On File	On File	
2	On File	On File	
3			
4			
5			
6			

Operator Information		
Name Dynamic Aviation Group, Inc	Operator Designator Code	Doing Business As

Street Address	City Bridgewater	State VA	Zip Code 22812
----------------	---------------------	-------------	-------------------

-Type of Certificate(s) Held:
Air Carrier Operating Certificate(s): Foreign Operation

Operating Certificate:	Operator Certificate:
------------------------	-----------------------


Regulation Flight Conducted Under: Non-U.S., Non-Commercial

Type of Flight Operations Conducted: Aerial Observation

Flight Plan/Itinerary			
Type of Flight Plan Filed: Unknown			

Last Departure Point Georgetown	State	Airport Identifier SYCJ	
Destination Local Flight	State	Airport Identifier SYCJ	

Weather Information			
Investigator's Source: Unknown	Facility ID:	Observation Time (Local):	
Sky/Lowest Cloud Condition:		Ft. AGL	
Lowest Ceiling:	Ft. AGL	Visibility:	SM Altimeter: "Hg

 <p>National Transportation Safety Board PRELIMINARY REPORT AVIATION</p>	NTSB ID: ERA09WA037	
	Occurrence Date: 11/01/2008	
	Occurrence Type: Accident	

Weather Information (Continued from page 2)

Temperature: °C	Dew Point: °C	Wind Direction:	
Wind Speed: Kts.	Gusts: Kts.	Weather Conditions at Accident Site:	

Administration Data

Notification From Foreign Government	Date
FAA District Office/Coordinator Dynamic Aviation Aaron Lorson	Investigator-In-Charge (IIC) Eric Alleyne