

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 77

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 77

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 1			
Oversight / IR			
130 - Inadequate suprevison / command and control	H - Health Physics	H - Health Physics	050-00482/2006-005
130 - Inadequate suprevison / command and control	M - Mechanical	H - Health Physics	050-00482/2007-003
Number of Items for this Docket: 2			
Percent of Total for this Docket: 3			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00482/2007-006
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00482/2007-004
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00482/2007-003
113 - Procedure / reference document development and maintenance L	G - Engineering	G - Design	050-00482/2007-002
Number of Items for this Docket: 5			
Percent of Total for this Docket: 6			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003
140 - Problem not completely or accurately identified	M - Mechanical	S - Surveillance	050-00482/2007-003
142 - Operating experience (OE) review LTA	D - Emergency Planning	Q - Fire Protection	050-00482/2007-006
142 - Operating experience (OE) review LTA	F - Fuel Handling	R - Refueling	050-00482/2006-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-004
142 - Operating experience (OE) review LTA	O - Operations	S - Surveillance	050-00482/2007-003
143 - Tracking / trending LTA	E - Electrical	M - Maintenance / Repair	050-00482/2007-003
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003
143 - Tracking / trending LTA	O - Operations	O - Control Room Ops	050-00482/2007-003
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00482/2006-005
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00482/2006-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00482/2007-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00482/2007-006
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 77

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 77

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / IR			
148 - Action not yet started or untimely	E - Electrical	S - Surveillance	050-00482/2007-006
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00482/2007-006
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00482/2007-006
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00482/2007-006
150 - Programmatic deficiency	H - Health Physics	H - Health Physics	050-00482/2007-002
Number of Items for this Docket: 20			
Percent of Total for this Docket: 26			
<hr/>			
Training / IR			
100 - Training LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-004
100 - Training LTA	O - Operations	S - Surveillance	050-00482/2007-003
Number of Items for this Docket: 2			
Percent of Total for this Docket: 3			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003
183 - Pre-job activities LTA	O - Operations	B - Bal of Plant Ops	050-00482/2007-002
185 - Procedural adherence LTA	C - Chemistry	Z - Other / Unknown	050-00482/2007-002
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00482/2007-006
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00482/2006-005
185 - Procedural adherence LTA	G - Engineering	T - Testing	050-00482/2007-003
185 - Procedural adherence LTA	M - Mechanical	B - Bal of Plant Ops	050-00482/2007-004
185 - Procedural adherence LTA	M - Mechanical	B - Bal of Plant Ops	050-00482/2007-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-006
185 - Procedural adherence LTA	M - Mechanical	T - Testing	050-00482/2007-003
185 - Procedural adherence LTA	O - Operations	B - Bal of Plant Ops	050-00482/2007-002
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00482/2006-005
185 - Procedural adherence LTA	O - Operations	T - Testing	050-00482/2007-003
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00482/2007-004
186 - Failure to take action / meet requirements	E - Electrical	S - Surveillance	050-00482/2007-006
186 - Failure to take action / meet requirements	O - Operations	S - Surveillance	050-00482/2007-003
187 - Action implementation LTA	D - Emergency Planning	Q - Fire Protection	050-00482/2007-006

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 77

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 77

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2007-006
187 - Action implementation LTA	G - Engineering	S - Surveillance	050-00482/2007-003
188 - Work practice or craft skill LTA	F - Fuel Handling	R - Refueling	050-00482/2006-005
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00482/2006-005
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00482/2007-002
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00482/2007-002
189 - Recognition of adverse condition / questioning attitude LTA	F - Fuel Handling	R - Refueling	050-00482/2006-005
189 - Recognition of adverse condition / questioning attitude LTA	G - Engineering	T - Testing	050-00482/2007-003
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-006
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	T - Testing	050-00482/2007-003
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	B - Bal of Plant Ops	050-00482/2007-006
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	T - Testing	050-00482/2007-003
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00482/2007-006
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00482/2007-004
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00482/2007-002
194 - Housekeeping LTA	D - Emergency Planning	Q - Fire Protection	050-00482/2007-004
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-004
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-006
195 - Logkeeping or log review LTA	O - Operations	O - Control Room Ops	050-00482/2007-002
197 - Self-check LTA	F - Fuel Handling	R - Refueling	050-00482/2006-005
197 - Self-check LTA	O - Operations	B - Bal of Plant Ops	050-00482/2007-002

Number of Items for this Docket: 47

Percent of Total for this Docket: 61

Total Items for this Docket: 77
