

**Attachment Twenty-Seven
Maintenance Sign-off Paperwork**

FORM #M001
DATE 01/06/03

Us Airways/Express/ Air Midwest
AIRCRAFT MAINTENANCE RECORD ~~LIT~~ HTS

PAGE 3 of 5
W/O# 05-1030106016

AIRCRAFT #: UE233 N233YV MAKE/MODEL: BEECHCRAFT MOD. 1900D

COPY

ACFT F.H.M.: 2263.8 ACFT T.T.: _____ ACFT CYCLES: _____

DISCREPANCY NATURE OF ACTION

13 Rt eng ignitors worn R+R Igniters on Rt Eng
IAW B1900 74-00-00 op ck
NORMA

PT/SN > ② CH 34055 DATE: 1-6-03 MECH: AM 708 INSP: N/A

RII 14 LEFT FUSE FUEL FILTER REQ CHANGE L/H FUEL FILTER CARTRIDGE REMOVED
REPLACED IAW BMM 28-20-10
LEAK? OP'S CK NORMAL

PT/SN > ① 03W1950231 ① M929513-233 DATE: 01-05-03 MECH: AM 705 INSP: DI 701

15 Quill shaft skewed REMOVED Quill shaft
TRANSCRIBED TO ADL#
24163

PT/SN > ② NA# 1593735 DATE: 1-06-03 MECH: AM 714 INSP: N/A

RII 16 Elevator rig pin installed REMOVED ELEVATOR RIG PIN
IAW BMM 27-30-00
ops check w/

PT/SN > _____ DATE: 1-06-03 MECH: AM 714 INSP: DI 701

RII 17 Rudder rig pin installed REMOVED Rudder RIG PIN
IAW BMM 27-20-00
ops check w/

PT/SN > _____ DATE: 1/5/03 MECH: AM 704 INSP: DI 701

RII 18 elevator cable tension low Adjusted elevator cable
Tension per BMM 27-30-02
ops check normal

PT/SN > ④ M921256-2 ④ M921256-2 PL 704 DATE: 1/5/03 MECH: AM 704 INSP: DI 701