

AIRPORT DIAGRAM

ATIS 127.65 270.1
SPRINGFIELD TOWER ★
121.3 257.8
GND CON
121.9 348.6
CLNC DEL
121.7

Rwy 13 Idg 6214'

RWY 4-22
S100, D200, ST175, DT350
RWY 13-31
S70, D90, ST114, DT160
RWY 18-36
S60, D70, ST89, DT130

Since October 1, 2006, there have been 5 runway incursions caused by pilots crossing hold short lines without authorization. Remember - eyes out when taxiing and when in doubt... ASK!


JANUARY 2005 ANNUAL RATE OF CHANGE 0.1°W

FIELD ELEV 597

EC-3, 18 DEC 2008 to 15 JAN 2009

EC-3, 18 DEC 2008 to 15 JAN 2009

After landing, make sure you exit onto a taxiway, not another runway!



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READEBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

89° 41'W

89° 40'W

AIRPORT DIAGRAM