

Honorable John H. Shaffer

-2-

of DME as a means of determining the location of fixes on the final approach course of the localizer.

This recommendation will be released to the public on the issue date shown above. No public dissemination of the contents of this document should be made prior to that date.

Reed, Chairman; Laurel, McAdams, Thayer and Burgess, Members, concurred in the above recommendation.

By: John H. Reed
Chairman