

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 21

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 21

Facility Name: Waterford 3 Docket (050- 00382)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00382/2006-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Oversight / IR			
130 - Inadequate supervision / command and control	O - Operations	O - Control Room Ops	050-00382/2006-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00382/2006-008
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00382/2006-008
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00382/2006-004
Number of Items for this Docket: 3			
Percent of Total for this Docket: 14			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	V - Troubleshooting	050-00382/2006-009
143 - Tracking / trending LTA	Z - Other / Unknown	Z - Other / Unknown	050-00382/2006-008
144 - Audit / self-assessment / effectiveness review LTA	Z - Other / Unknown	Z - Other / Unknown	050-00382/2006-008
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00382/2006-008
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00382/2006-003
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00382/2006-003
Number of Items for this Docket: 6			
Percent of Total for this Docket: 29			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00382/2006-004
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00382/2006-009
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00382/2006-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00382/2006-004
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00382/2006-010
187 - Action implementation LTA	G - Engineering	G - Design	050-00382/2006-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00382/2006-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00382/2006-009
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00382/2005-005

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 21
National Average: 43
2x National Average: 86
National Median: 24
Average for Selected Dockets: 21

Facility Name: Waterford 3 Docket (050- 00382)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
190 - Failure to stop work / non-conservative decision making	M - Mechanical	V - Troubleshooting	050-00382/2006-009
Number of Items for this Docket: 10			
Percent of Total for this Docket: 48			

Total Items for this Docket: 21
