

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 15

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 15

Facility Name: Vermont Yankee Docket (050- 00271)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	H - Health Physics	H - Health Physics	050-00271/2007-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
<hr/>			
Oversight / IR			
130 - Inadequate suprevison / command and control	Y - Shipping / transportation	Y - Shipping / transportatic	050-00271/2007-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	Y - Shipping / transportation	Y - Shipping / transportatic	050-00271/2007-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
<hr/>			
Problem Identification & Resolution / IR			
146 - Evaluation LTA	G - Engineering	G - Design	050-00271/2007-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00271/2007-002
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00271/2007-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00271/2007-002
185 - Procedural adherence LTA	O - Operations	S - Surveillance	050-00271/2007-002
186 - Failure to take action / meet requirements	Y - Shipping / transportation	Y - Shipping / transportatic	050-00271/2007-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00271/2007-002
189 - Recognition of adverse condition / questioning attitude LTA	Y - Shipping / transportation	Y - Shipping / transportatic	050-00271/2007-009
Number of Items for this Docket: 7			
Percent of Total for this Docket: 47			
<hr/>			
Procedures & Reference Document / LER			
110 - No procedure / reference documents	M - Mechanical	M - Maintenance / Repair	050-00271/2007-003-00
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00271/2007-002-01
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00271/2007-001-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 15
National Average: 41
2x National Average: 82
National Median: 24
Average for Selected Dockets: 15

Facility Name: Vermont Yankee Docket (050- 00271)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
112 - Procedure / reference document contains human factors deficienc	I - Instrumentation & Control	S - Surveillance	050-00271/2007-001-00
Number of Items for this Docket: 4			
Percent of Total for this Docket: 27			

Total Items for this Docket: 15
