



HighTech, Inc. STEP 3A. Electronic Hardware Development Process 9/26/2007 Version 1.0



	HighTech, Inc.	
STEP 3B. Embedded Software/Firmware Development Process	9/26/2007	Version 1.0



Requirements Review

Assess requirements for completeness:

- * input/output data ranges, units, and accuracy,
- * safety critical variables identification and use,
- * TBD's addressed

Computer-Aided Software Engineering (CASE) Diagrams

Data dictionary Control flow digrams Data flow diagrams State transition diagrams Calling Structure

Coding Conventions

Follow code writing conventions, for example:

- * variable initialization and naming,
- * In-line documentation,
- * module size and fan in/fan out limitations,
- * Disallowed constructs (e.g. use of pointer arithmitic),
- * use of assertions such as pre-conditions and post-conditons, exception handling

Test Procedures

- * static analysis of code
 - safety-critical data flow
 - adherence to coding conventions
- * dynamic execution of code
 - multiple condition coverage
 - boundary value
 - sequencing/state transition tests
 - nominal and off-nominal tests
 - timing tests

Test Levels

- * function/utility libraries
- * unit (subroutine)
- * module or object
- * sub-frame (part of a Sense-Process-

Actuate) sequence

* frame (all of a Sense-Process-

Actuate) sequence



