

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**Boeing:** Docket No. FAA-2007-28160; Directorate Identifier 2007-NM-006-AD.

#### Comments Due Date

(a) The FAA must receive comments on this AD action by July 2, 2007.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to Boeing Model 757-200 and 757-300 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 757-30-0024, dated July 24, 2006.

#### Unsafe Condition

(d) This AD results from a report of charred insulation blankets and burned wires around the forward gray water composite drain mast found during an inspection of the forward cargo compartment on a Model 767-300F airplane. We are issuing this AD to prevent a fire near a composite drain mast and possible disruption of the electrical power system due to a lightning strike on a composite drain mast, which could result in the loss of several functions essential for safe flight.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Bonding Jumper Installation

(f) Within 60 months after the effective date of this AD: Install a 135-ampere copper bonding jumper between a ground and the clamp on the tube of the forward and aft gray water composite drain mast, in accordance with the Accomplishment instructions of Boeing Special Attention Service Bulletin 757-30-0024, dated July 24, 2006.

#### Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on May 7, 2007.

**Stephen P. Boyd,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-9390 Filed 5-15-07; 8:45 am]

**BILLING CODE 4910-13-P**

#### DEPARTMENT OF HOMELAND SECURITY

##### Coast Guard

##### 33 CFR Part 100

**[USCG-2007-27373](Formerly [USCG-2207-2737])**

**RIN 1625-AA08**

#### Regattas and Marine Parades; Great Lakes Annual Marine Events

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of proposed rulemaking; correction.

**SUMMARY:** This document contains a correction to the docket number of the Notice of Proposed Rulemaking entitled "Regattas and Marine Parades; Great Lakes Annual Marine Events" published on April 6, 2007, in the **Federal Register** (72 FR 17062).

**DATES:** The NPRM is corrected as of May 16, 2007.

**ADDRESSES:** You may submit comments identified by Coast Guard docket number USCG-2007-27373 to the Docket Management Facility at the U.S. Department of Transportation. Two different locations are listed under the mail and delivery options below because the Document Management Facility is moving May 30, 2007. To avoid duplication, please use only one of the following methods:

(1) *Web site:* <http://dms.dot.gov>.

(2) *Mail:*

• Address mail to be delivered before May 30, 2007, as follows: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Washington, DC 20590-0001.

• Address mail to be delivered on or after May 30, 2007, as follows: Docket

Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590.

(3) *Fax:* 202-493-2251.

(4) *Delivery:*

• Before May 30, 2007, deliver comments to: Room PL-401 on the Plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC 20590.

• On or after May 30, 2007, deliver comments to: Room W12-140 on the Ground Floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC 20590.

At either location, deliveries may be made between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202-366-9329.

(5) *Federal eRulemaking Portal:*

<http://www.regulations.gov>.

#### FOR FURTHER INFORMATION CONTACT:

Amy Bunk, Attorney-Advisor, Coast Guard, 2100 Second Street, SW., Washington, DC 20593 at 202-372-3864.

**SUPPLEMENTARY INFORMATION:** On April 6, 2007, the Coast Guard published a Notice of Proposed Rulemaking entitled "Regattas and Marine Parades; Great Lakes Annual Marine Events" **Federal Register** (72 FR 17062). In that document the last digit of the docket number USCG-2007-2737 was inadvertently shortened. The correct docket number for this NRPM is USCG-2007-27373.

In rule FR Doc. E7-6425 published on April 6, 2007, (72 FR 17062) make the following corrections:

1. On page 17062, in the first column, in the heading change the docket number to read as follows: "[USCG-2007-27373]"

Dated: May 9, 2007.

**Stefan G. Venckus,**

*Chief, Office of Regulations and Administrative Law, United States Coast Guard.*

[FR Doc. E7-9349 Filed 5-15-07; 8:45 am]

**BILLING CODE 4910-15-P**

#### DEPARTMENT OF THE INTERIOR

##### National Park Service

##### 36 CFR Part 7

**RIN 1024-AD55**

#### Special Regulations; Areas of the National Park System

**AGENCY:** National Park Service, Interior.

**ACTION:** Proposed rule.