deviation will facilitate maintenance work on the bridge that is essential to the continued safe operation of the drawbridge.

DATES: This temporary deviation is effective from 8 a.m., January 15, 2004, until 8 a.m., February 29, 2004. ADDRESSES: Materials referred to in this notice are available for inspection or copying at the office of the Eighth Coast Guard District, Bridge Administration Branch, Commander (obr), Eighth Coast Guard District, 1222 Spruce Street, St. Louis, MO 63103–2832, between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays. The Bridge Administration Branch maintains the public docket for this temporary deviation.

## FOR FURTHER INFORMATION CONTACT:

Roger K. Wiebusch, Bridge Administrator, Commander (obr), Eighth Coast Guard District, 1222 Spruce Street, St. Louis, MO 63103–2832, (314) 539–3900, extension 2378.

SUPPLEMENTARY INFORMATION: The Kansas City Southern Railway Company requested a temporary deviation on December 15, 2003 for the operation of the drawbridge to allow the bridge owner time for preventative maintenance. Presently, the draw opens on signal for passage of river traffic. This deviation allows the bridge to remain closed to navigation for 46 days from 8 a.m., January 15, 2004, until 8 a.m., February 29, 2004, Central Standard Time. Vessels not exceeding the vertical clearance of the drawbridge may pass under the drawbridge during repairs. There are no alternate routes for vessels transiting through mile 282.1, Upper Mississippi River.

The Louisiana Railroad Drawbridge provides a vertical clearance of 15.8 feet above normal pool in the closed to navigation position. Navigation on the waterway consists primarily of commercial tows and recreational watercraft. In order to repair the four large wedge cylinders, the bridge must be kept inoperative and in the closed to navigation position. This deviation has been coordinated with waterway users. No objections were received.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: January 20, 2004.

Roger K. Wiebusch,

Bridge Administrator.

[FR Doc. 04–1643 Filed 1–26–04; 8:45 am] BILLING CODE 4910–15–P

# DEPARTMENT OF HOMELAND SECURITY

## **Coast Guard**

33 CFR Part 117

[CGD13-04-001]

## Drawbridge Operation Regulations; Hoquiam River, Aberdeen, WA

**AGENCY:** Coast Guard, DHS. **ACTION:** Notice of temporary deviation from regulations.

**SUMMARY:** The Commander, Thirteenth Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the Simpson Avenue Drawbridge at mile 0.5 and the Riverside Avenue Drawbridge at mile 0.9 across the Hoquiam River at Aberdeen, Washington. This deviation allows the bridges to temporarily operate on two-hour notice for all openings for vessels. The deviation is necessary to facilitate seismic retrofit of the structures.

**DATES:** This deviation is effective from 6 a.m., February 16 through 6 p.m., April 15, 2004.

ADDRESSES: Materials referred to in this document are available for inspection or copying at Commander (oan), Thirteenth Coast Guard District, 915 Second Avenue, Seattle, Washington 98174–1067 between 7:45 a.m. and 4:15 p.m., Monday through Friday, except Federal holidays. The telephone number is (206) 220–7270. The Bridge Section of the Aids to Navigation and Waterways Management Branch maintains the public docket for this temporary deviation.

FOR FURTHER INFORMATION CONTACT: Austin Pratt, Chief, Bridge Section, Aids to Navigation and Waterways Management Branch, (206) 220–7282.

**SUPPLEMENTARY INFORMATION:** Washington State Department of Transportation (WSDOT) requested this deviation from normal operations to facilitate seismic retrofit. The containment system for contaminants and other equipment must be modified or removed in order to operate the movable spans. Currently, the draws need not open for the passage of vessels unless one hour notice is provided at all times. Vessels on the related reach of the waterway should be able to provide at least two hours notice for openings without unreasonable inconvenience.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: January 20, 2004.

#### Jeffrey M. Garrett,

Rear Admiral, U.S. Coast Guard, Commander, Thirteenth Coast Guard District. [FR Doc. 04–1644 Filed 1–26–04; 8:45 am] BILLING CODE 4910–15–P

## DEPARTMENT OF HOMELAND SECURITY

**Coast Guard** 

33 CFR Parts 148, 149, and 150

[USCG-1998-3884]

RIN 1625-AA20 (formerly RIN 2115-AF63)

## **Deepwater Ports; Correction**

**AGENCY:** Coast Guard, DHS.

**ACTION:** Temporary interim rule; correction.

**SUMMARY:** On January 6, 2004, the Coast Guard published a temporary interim rule with request for comments in the **Federal Register**, which inadvertently contained errors in the table of contents for 33 CFR part 149 and in paragraph designations for 33 CFR 149.415. This document corrects those errors.

DATES: Effective on January 27, 2004.

FOR FURTHER INFORMATION CONTACT: Lieutenant Commander Kevin Tone, Vessel and Facility Operating Standards Division (G–MSO–2), Coast Guard, telephone 202–267–0226.

**SUPPLEMENTARY INFORMATION:** The Coast Guard published a temporary interim rule with request for comments in the **Federal Register** of January 6, 2004 (69 FR 724; FR Doc. 03–32204). The rule contained inadvertent errors in the table of contents to 33 CFR part 149 and in paragraph designations for 33 CFR 149.415. These errors are nonsubstantive, but we are correcting them to prevent unnecessary confusion.

# PART 149—[CORRECTED]

■ In temporary interim rule FR Doc. 03– 32204 published on January 6, 2004 (69 FR 724), make the following corrections. On page 761, in the third column, remove the words "149.150 What are the requirements for the receipt of oil residues from vessels?" On page 769, in the second column under § 149.415, redesignate paragraphs (d) and (e) as paragraphs (c) and (d) respectively.

3836