



United States  
Department of  
Agriculture

Forest  
Service

Lake Tahoe Basin Management  
Unit

35 College Drive  
South Lake Tahoe, CA 96150  
(530) 543-2600

---

File Code: 1950

Date: August 4, 2008

To: File

Subject: Angora Hazard Tree Removal Project-Map Correction


This memo identifies a mapping correction to the Angora Hazard Tree Removal Project in Unit 5 as Described in the Decision Memo (3-21-2008). As shown on the attached map, the original map location of road from Pyramid Circle found in the Decision Memo is identified as being incorrect. The Previously Incorrect Mapped route is decommissioned, and is not present on the ground. As a result of the error, the existing road alignment (present on the ground) that is analyzed in the project is identified as the Correct Map Location. The project environmental analysis is not changed or affected as a result of the mapping error. There were no comments during scoping or public comment that indicated the previously mapped route as being incorrect. The existing road alignment was analyzed by the project interdisciplinary team with corresponding design features, mitigation measures, and Best Management Practices applying to the existing road alignment. I have reviewed the mapping error and approve the correction that is now shown on the map.

Sincerely,

TERRI MARCERON  
Forest Supervisor



# Angora Hazard Tree Removal Project Road Map Correction



July 08

