




## Structurally Deficient Bridges on the National Highway System New Hampshire - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 46 structurally deficient NHS bridges in New Hampshire, 0 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	16801110011500	FEE TPK	0.8 MI FROM BABOOSIC RD
2	16101530006100	I-293 RAMP	1.5 E JCT RT 28
3	16101490006300	I-293,FEE TPK	.6 MI BEDFORD TL.
4	16101460006400	I-293,FEE TPK	.8 MI BEDFORD T.L.
5	16101460006500	I-293,FEE TPK SPUR	.7 MI BEDFORD T.L.
6	16101440006600	I-293,FEE TPK	.3 MI SECOND ST
7	16101340006700	I-293,FEE TPK	.7 MI JCT RT 3
8	1901890012100	US 3	.6 MI JCT RT 101
9	16100600008600	I-93 SB	MANCHESTER-HOOKSETT TL
10	15400960016300	I-93 SB	1.5 MI S MANCHESTER CL
11	15400970016300	I-93 NB	1.5 MI S MANCHESTER CL
12	15400990016000	I-93 SB	1.7 MI S MANCHESTER CL
13	15401000016000	I-93 NB	1.7 MI S MANCHESTER TL
14	1701880012300	US302	2.0 MI SW OF ROUTE 16
15	20401370029700	NH 16,NH 25	2.0 MI SO. TAMWORTH T.L.
16	20401370029900	NH 16,NH 25	2.3 MI TAMWORTH T.L.
17	20401520026800	NH 16,NH 25	4.3 MI TAMWORTH T.L.
18	22201580011000	SP TPK,NH 16 SB	1.8 MI FROM JCT RT 125
19	22201570011000	SP TPK,NH 16 NB	3.2 MI N DOVER TL
20	21701830008700	NH 33	.6MI FROM JCT RT 1
21	21701730007100	US 1 SB	0.4 MI FROM JCT RT 101
22	21702460008300	US 1	0.1 MI SOUTH MAINE-NH SL