




Structurally Deficient Bridges on the National Highway System New Hampshire - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 46 structurally deficient NHS bridges in New Hampshire, 0 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	13601050006700	NH 9	3.2 MI E WESTMORELAND TL
2	14401560011700	I-89 NB	2.5 MI FROM ENFIELD T.L.
3	24600930006100	NH 9	0.5 MI SW TO ROXBURY TL
4	18801240005800	I-89 SB	.3 MI FROM SUTTON TL
5	18801240005900	I-89 NB	0.3 MI FROM SUTTON TL
6	25300940011400	NH101	1.6 MI FROM WILTON TL
7	26302430016600	I-89 SB	1.0 MI HOPKINTON TL
8	26302440016700	I-89 NB	1.0 MI HOPKINTON T.L.
9	5201630010600	I-93,FEE TPK	1.6 MI N JCT RTE 3
10	2701350016000	I-93,FEE TPK SB	BOW INTERCHANGE
11	2701360016000	I-93,FEE TPK NB	BOW INTERCHANGE
12	400690005600	US 3	PEMBROKE-ALLENSTOWN TL
13	28001340010100	I-93 SB	.5 MI N OF JCT RT 111 A
14	28001350009000	I-93 SB	0.5 MI S JCT RT 111
15	22800680007800	I-93 SB	1.1 MI N OF JCT RT 38
16	22800700007900	I-93 NB	1.1 MI N OF JCT RT 38
17	22800730006300	I-93 SB	2.0 MI N. OF MASS SL
18	22800770006300	I-93 NB	2.0MI N OF MASS SL.
19	22800810005500	I-93(RAMP B)	.2 MI S OF JCT NH 38
20	22800800005600	I-93(RAMP D)	.2 MI S OF JCT NH 38
21	22800820005700	I-93(RAMP B)	.2 MI S OF JCT NH 38
22	22800810005800	I-93(RAMP D)	.2 MI S OF JCT NH 38
23	22800840006100	I-93(RAMP A)	.4MI S OF JCT RT 38