

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 35

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 35

---

**Facility Name: Turkey Point 3 Docket (050- 00250)**

Details	Department	Work Type	Docket/Report
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	M - Mechanical	G - Design	050-00250/2005-002
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00250/2005-002
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 6</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
142 - Operating experience (OE) review LTA	Z - Other / Unknown	B - Bal of Plant Ops	050-00250/2005-003
147 - Individual corrective action LTA	G - Engineering	M - Maintenance / Repair	050-00250/2004-005
147 - Individual corrective action LTA	G - Engineering	M - Maintenance / Repair	050-00250/2004-005
147 - Individual corrective action LTA	G - Engineering	M - Maintenance / Repair	050-00250/2004-005
147 - Individual corrective action LTA	G - Engineering	M - Maintenance / Repair	050-00250/2004-005
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00250/2005-004
148 - Action not yet started or untimely	M - Mechanical	T - Testing	050-00250/2005-004
148 - Action not yet started or untimely	O - Operations	O - Control Room Ops	050-00250/2005-004
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00250/2005-002
<b>Number of Items for this Docket: 9</b>			
<b>Percent of Total for this Docket: 26</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
183 - Pre-job activities LTA	M - Mechanical	S - Surveillance	050-00250/2005-004
188 - Work practice or craft skill LTA	D - Emergency Planning	D - Emergency Drill	050-00250/2005-010
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00250/2005-002
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	O - Control Room Ops	050-00250/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	T - Testing	050-00250/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	T - Testing	050-00250/2005-004
188 - Work practice or craft skill LTA	O - Operations	B - Bal of Plant Ops	050-00250/2005-010
188 - Work practice or craft skill LTA	O - Operations	Q - Fire Protection	050-00250/2005-010
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00250/2005-004
190 - Failure to stop work / non-conservative decision making	Q - Quality assurance / oversight	F - Modification	050-00250/2004-005

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 35

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 35

---

**Facility Name: Turkey Point 3 Docket (050- 00250)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
198 - Worker distracted / interrupted	Z - Other / Unknown	B - Bal of Plant Ops	050-00250/2005-003
<b>Number of Items for this Docket:</b> 15			
<b>Percent of Total for this Docket:</b> 43			
<b>Communication / LER</b>			
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00250/2005-001-00
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00250/2005-001-00
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00250/2005-001-00
<b>Number of Items for this Docket:</b> 3			
<b>Percent of Total for this Docket:</b> 9			
<b>Oversight / LER</b>			
130 - Inadequate supervision / command and control	Q - Quality assurance / oversight	M - Maintenance / Repair	050-00250/2005-006-00
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 3			
<b>Procedures &amp; Reference Document / LER</b>			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00250/2005-005-00
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00250/2005-006-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 6			
<b>Work Planning &amp; Practices / LER</b>			
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2005-006-00
190 - Failure to stop work / non-conservative decision making	W - Work Control / Scheduling Outage Pla	T - Testing	050-00250/2005-002-00
196 - Independent verification / plant tours LTA	W - Work Control / Scheduling Outage Pla	T - Testing	050-00250/2005-002-00
<b>Number of Items for this Docket:</b> 3			
<b>Percent of Total for this Docket:</b> 9			
<b>Total Items for this Docket:</b> 35			

---