




Structurally Deficient Bridges on the National Highway System New Jersey - Congressional District 07



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 17 structurally deficient NHS bridges in New Jersey, 8 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1014150	I78 EB	0.5 MI E OF COUNTY LINE
2	1013158	RT31	0.3 MI N OF MAIN Street
3	1017150	RAMP E	.2 MI E OF I-78,EXIT-16
4	1018150	I-78 RAMP A	.8 MI EAST OF RT 31
5	1810156	ROUTE US 206	4.7 MI N OF CO. 518 JCT
6	1810155	US 206	.5 MILE NORTH OF 604 JCT
7	1817153	I78 EB	AT I-287 INTERCHANGE
8	1817156	I-78 WB	AT I-78,EXIT-29
9	1817167	I-78 W.B.	6.25 MI EAST OF I-287 JCT
10	1806156	RT.28	1.65 MI EAST OF RTE 287
11	1231158	I-287 NB	1.3 MILE SOUTH OF 529
12	1231159	I-287 SB	1.43 MILE SO OF 529 JCT
13	2010161	I78 WB	0.9 MI W OF 78-24 JCT
14	361272T	GARDEN ST PARKWAY	0.5 MI SOUTH OF ROUTE 440
15	1210154	RT US 9 SB	.4 MI SO.RT.US9 &RT41 JCT
16	1205150	US 1&9	0.5 MI N OF US1-US9 JCT
17	1210150	US RT 9	0.8 MI SOUTH OF RT 1 JCT.