

Corrections

Federal Register

Vol. 67, No. 224

Wednesday, November 20, 2002

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

DEPARTMENT OF AGRICULTURE

Forest Service

Establishment of Stumpy Point Purchase Unit, Phillips and Lee Counties, AR

Correction

In notice document 02-28757 beginning on page 68831 in the issue of Wednesday, November 13, 2002, make the following correction:

On page 68831, in the third column, the subject heading is correct to read as set forth above.

[FR Doc. C2-28757 Filed 11-19-02; 8:45 am]

BILLING CODE 1505-01-D

DEPARTMENT OF TRANSPORTATION

Research and Special Programs Administration

49 CFR Part 195

[Docket No. RSPA-97-2762; Amdt. 195-73]

RIN 2137-AD24

Controlling Corrosion on Hazardous Liquid and Carbon Dioxide Pipelines

Correction

In rule document 01-31655 beginning on page 66994 in the issue of Thursday, December 27, 2001, make the following correction:

§ 195.573 [Corrected]

On page 67006, in § 195.573 (c), in the first column, the table is corrected to read as set forth below.

Device	Check frequency
Rectifier	At least six times each calendar year, but with intervals not exceeding 2½ months.
Reverse current switch.	
Diode	
Interference bond whose failure would jeopardize structural protection.	
Other interference bond.	At least once each calendar year, but with intervals not exceeding 15 months.

[FR Doc. C1-31655 Filed 11-19-02; 8:45 am]

BILLING CODE 1505-01-D