
Corrections

Federal Register

Vol. 69, No. 16

Monday, January 26, 2004

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-266-AD; Amendment 39-13388; AD 2003-25-05]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 Airplanes

Correction

In rule document 03-31058 beginning on page 70428 in the issue of Thursday,

December 18, 2003 make the following correction:

§39.13 [Corrected]

On page 70429, in §39.13, in the second column, under paragraph (a)(2), in the last line, “exceed 50 flight hours” should read, “exceed 500 flight hours”.

[FR Doc. C3-31058 Filed 1-23-04; 8:45 am]

BILLING CODE 1505-01-D