

2000 Human Factors Information System Report for Plant Docket 331

Combined IR/ER/LER Report
Docket: 50-331 DUANE ARNOLD

Total Number of Hits in Date Range: 61
From 01/01/2000 to 12/31/2000
2x National Average: 144

Details	Department	Work Type	Docket/Report
Communications IR			
Number of items: 3			
Percent of total: 4.92			
54-No communication	Z-Other	Z-Other	50-331/2000004
	Z-Other		
54-No communication	Z-Other	Z-Other	50-331/2000004
	Z-Other		
53-Communication LT	Z-Other	D-Emergency Drill	50-331/2000011
	Z-Other		
Communications ER			
Number of items: 0			
Percent of total: 0			
Communications LER			
Number of items: 1			
Percent of total: 1.64			
54-No communication	W-Work Control / Sc M-Maint / Repair		50-331/200000300
	G-Engineering		
Human-System Interface and Environm IR			
Number of items: 6			
Percent of total: 9.84			
64-Placement or loc	Z-Other	Z-Other	50-331/2000011
64-Placement or loc	Z-Other	Z-Other	50-331/2000011
64-Placement or loc	Z-Other	Z-Other	50-331/2000011
67-Function LTA (ac	Z-Other	Z-Other	50-331/2000011
67-Function LTA (ac	Z-Other	Z-Other	50-331/2000011
67-Function LTA (ac	Z-Other	Z-Other	50-331/2000011
Human-System Interface and Environm ER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm LER			
Number of items: 1			
Percent of total: 1.64			
64-Placement or loc	I-Instrumentation & C-Calibration		50-331/200000100
Management and Supervision IR			
Number of items: 1			
Percent of total: 1.64			
47-Root Cause LTA	G-Engineering	Z-Other	50-331/1999015
Management and Supervision ER			
Number of items: 0			
Percent of total: 0			
Management and Supervision LER			
Number of items: 2			
Percent of total: 3.28			
33-Management expec	I-Instrumentation & C-Calibration		50-331/200000100

Page: 1 Date:06/03/2002

Combined IR/ER/LER Report
Docket: 50-331 DUANE ARNOLD

Total Number of Hits in Date Range: 61
 From 01/01/2000 to 12/31/2000
 2x National Average: 144

Details	Department	Work Type	Docket/Report
Management and Supervision LER			
Number of items: 2			
Percent of Total: 3.28			
43-Operating Experi	I-Instrumentation & C-Calibration		50-331/200000100
Organizational Issues IR			
Number of items: 0			
Percent of total: 0			
Organizational Issues ER			
Number of items: 0			
Percent of total: 0			
Organizational Issues LER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document IR			
Number of items: 12			
Percent of total: 19.67			
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/1999015
13-Procedure has hu	G-Engineering	G-Design	50-331/1999015
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000002
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000002
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000002
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000002
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000002
11-No procedure / r	P-Procedure Writers	Q-Fire Protection	50-331/2000003
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000003
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000004
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000004
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-331/2000004
11-No procedure / r	Z-Other	Z-Other	50-331/2000004
Procedures and Reference Document ER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document LER			
Number of items: 2			
Percent of total: 3.28			
12-Procedure techni	I-Instrumentation & C-Calibration		50-331/200000100
12-Procedure techni	I-Instrumentation & C-Calibration		50-331/200000100
Training IR			
Number of items: 4			
Percent of total: 6.56			
02-Training LTA	T-Training	S-Surveillance	50-331/2000009
05-Individual knowl	Z-Other	Z-Other	50-331/2000011
05-Individual knowl	Z-Other	Z-Other	50-331/2000011
05-Individual knowl	Z-Other	Z-Other	50-331/2000011
Training ER			
Number of items: 0			
Percent of total: 0			
Training LER			
Number of items: 3			
Percent of total: 4.92			
02-Training LTA	I-Instrumentation & C-Calibration		50-331/200000100

Combined IR/ER/LER Report
 Docket: 50-331 DUANE ARNOLD

Total Number of Hits in Date Range: 61
 From 01/01/2000 to 12/31/2000

2x National Average: 144

Details	Department	Work Type	Docket/Report
Training LER			
Number of items: 3			
Percent of Total: 4.92			
02-Training LTA	I-Instrumentation &	C-Calibration	50-331/200000100
05-Individual knowl	G-Engineering	M-Maint / Repair	50-331/200000300

Work Factors IR			
Number of items: 21			
Percent of total: 34.43			
84-Non-conserv. dec	O-Operations	B-Bal of Plant Ops	50-331/1999015
84-Non-conserv. dec	O-Operations	B-Bal of Plant Ops	50-331/1999015
83-Work practice or	O-Operations	B-Bal of Plant Ops	50-331/1999015
92-Self check LTA	O-Operations	B-Bal of Plant Ops	50-331/1999015
93-Awareness or att	M-Mechanical	H-Health Physics	50-331/1999015
93-Awareness or att	M-Mechanical	H-Health Physics	50-331/1999015
84-Non-conserv. dec	P-Procedure Writers	P-Procedure Dev	50-331/1999015
93-Awareness or att	I-Instrumentation &	A-Administrative	50-331/1999015
93-Awareness or att	I-Instrumentation &	M-Maint / Repair	50-331/1999015
82-Briefing, prep.	I-Instrumentation &	M-Maint / Repair	50-331/1999015
92-Self check LTA	I-Instrumentation &	S-Surveillance	50-331/1999015
89-Housekeeping LTA	E-Electrical	M-Maint / Repair	50-331/2000001
83-Work practice or	E-Electrical	M-Maint / Repair	50-331/2000001
93-Awareness or att	D-Emergency Plannin	D-Emergency Drill	50-331/2000001
84-Non-conserv. dec	Z-Other	A-Administrative	50-331/2000002
84-Non-conserv. dec	Z-Other	A-Administrative	50-331/2000002
84-Non-conserv. dec	G-Engineering	Q-Fire Protection	50-331/2000003
84-Non-conserv. dec	Z-Other	Z-Other	50-331/2000004
83-Work practice or	Z-Other	D-Emergency Drill	50-331/2000011
84-Non-conserv. dec	Z-Other	Z-Other	50-331/2000011
93-Awareness or att	Z-Other	P-Procedure Dev	50-331/2000012

Work Factors ER
Number of items: 0
Percent of total: 0

Work Factors LER			
Number of items: 5			
Percent of total: 8.2			
82-Briefing, prep.	I-Instrumentation &	C-Calibration	50-331/200000100
92-Self check LTA	I-Instrumentation &	C-Calibration	50-331/200000100
84-Non-conserv. dec	W-Work Control / Sc	M-Maint / Repair	50-331/200000300
91-Verification / p	W-Work Control / Sc	M-Maint / Repair	50-331/200000300
81-Work Package Qua	I-Instrumentation &	M-Maint / Repair	50-331/200000300

Page: 3

Date:06/03/2002

[End of File for Plant Docket 331 (2000)]