

Proposed Rules

Federal Register

Vol. 72, No. 97

Monday, May 21, 2007

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

NUCLEAR REGULATORY COMMISSION

10 CFR Part 1

RIN 3150-A117

Emergency Preparedness Policies Developed for Nuclear Materials Facilities

AGENCY: Nuclear Regulatory Commission.

ACTION: Proposed rule.

SUMMARY: The Nuclear Regulatory Commission (NRC) is proposing to amend its regulations that govern organization and functions of NRC offices. This action is necessary to clarify emergency preparedness program responsibilities of the Office of Nuclear Security and Incident Response. The current limiting reference of "nuclear reactors" would be replaced with the phrase "nuclear facilities."

DATES: Comments on the proposed rule must be received on or before June 20, 2007.

ADDRESSES: You may submit comments by any one of the following methods. Please include the following number (RIN 3150-A117) in the subject line of your comments. Comments on rulemakings submitted in writing or in electronic form will be made available for public inspection. Because your comments will not be edited to remove any identifying or contact information, the NRC cautions you against including personal information such as social security numbers and birth dates in your submission.

Mail comments to: Secretary, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, ATTN: Rulemakings and Adjudications Staff.

E-mail comments to: SECY@nrc.gov. If you do not receive a reply e-mail confirming that we have received your comments, contact us directly at (301) 415-1966. You may also submit comments via the NRC's rulemaking Web site at <http://ruleforum.llnl.gov>. Address questions about our rulemaking

Web site to Carol Gallagher (301) 415-5905; e-mail cag@nrc.gov. Comments can also be submitted via the Federal eRulemaking Portal <http://www.regulations.gov>.

Hand deliver comments to: 11555 Rockville Pike, Rockville, Maryland 20852, between 7:30 a.m. and 4:15 p.m. Federal workdays. (Telephone (301) 415-1966).

Fax comments to: Secretary, U.S. Nuclear Regulatory Commission at (301) 415-1101.

Publicly available documents related to this rulemaking may be viewed electronically on the public computers located at the NRC's Public Document Room (PDR), O1 F21, One White Flint North, 11555 Rockville Pike, Rockville, Maryland. The PDR reproduction contractor will copy documents for a fee. Selected documents, including comments, may be viewed and downloaded electronically via the NRC rulemaking Web site at <http://ruleforum.llnl.gov>.

Publicly available documents created or received at the NRC after November 1, 1999, are available electronically at the NRC's Electronic Reading Room at <http://www.nrc.gov/reading-rm/adams.html>. From this site, the public can gain entry into the NRC's Agencywide Document Access and Management System (ADAMS), which provides text and image files of NRC's public documents. If you do not have access to ADAMS or if there are problems in accessing the documents located in ADAMS, contact the NRC PDR Reference staff at 1-800-397-4209, 301-415-4737 or by e-mail to pdr@nrc.gov.

FOR FURTHER INFORMATION CONTACT:

Kevin R. O'Sullivan, Office of Federal and State Materials and Environmental Management Programs, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, telephone (301) 415-8112, e-mail kro2@nrc.gov.

SUPPLEMENTARY INFORMATION: For additional information see the Direct Final Rule published in the final rules section of this **Federal Register**.

Procedural Background

Because the NRC considers this action non-controversial and routine, the NRC is publishing this proposed rule concurrently as a direct final rule. The direct final rule will become effective on August 6, 2007. However, if the NRC

receives significant adverse comments on the direct final rule by June 20, 2007, then the NRC will publish a document to withdraw the direct final rule. If the direct final rule is withdrawn, the NRC will address the comments received in response to the proposed revisions in a subsequent final rule. Absent significant modifications to the proposed revisions requiring republication, the NRC will not initiate a second comment period for this action if the direct final rule is withdrawn.

A significant adverse comment is a comment where the commenter explains why the rule would be inappropriate, including challenges to the rule's underlying premise or approach, or would be ineffective or unacceptable without a change. A comment is adverse and significant if:

(1) The comment opposes the rule and provides a reason sufficient to require a substantive response in a notice-and-comment process. For example, a substantive response is required when:

(A) The comment causes the NRC staff to reevaluate (or reconsider) its position or conduct additional analysis;

(B) The comment raises an issue serious enough to warrant a substantive response to clarify or complete the record; or

(C) The comment raises a relevant issue that was not previously addressed or considered by the NRC staff.

(2) The comment proposes a change or an addition to the rule, and it is apparent that the rule would be ineffective or unacceptable without incorporation of the change or addition.

(3) The comment causes the staff to make a change (other than editorial) to the rule.

List of Subjects in 10 CFR Part 1

Organization and function (Government agencies).

For the reasons set out in the preamble and under the authority of the Atomic Energy Act of 1954, as amended; the Energy Reorganization Act of 1974, as amended; and 5 U.S.C. 553; the NRC is proposing to adopt the following amendments to 10 CFR part 1.

PART 1—STATEMENT OF ORGANIZATION AND GENERAL INFORMATION

1. The authority citation for part 1 continues to read as follows:

Authority: Secs. 23, 161, 68 Stat. 925, 948, as amended (42 U.S.C. 2033, 2201); sec. 29, Pub. L. 85-256, 71 Stat. 579, Pub. L. 95-209, 91 Stat. 1483 (42 U.S.C. 2039); sec. 191, Pub. L. 87-615, 76 Stat. 409 (42 U.S.C. 2241); secs. 201, 203, 204, 205, 209, 88 Stat. 1242, 1244, 1245, 1246, 1248, as amended (42 U.S.C. 5841, 5843, 5844, 5845, 5849); 5 U.S.C. 552, 553; Reorganization Plan No. 1 of 1980, 45 FR 40561, June 16, 1980.

2. In § 1.46, paragraph (c) is revised to read as follows:

§ 1.46 Office of Nuclear Security and Incident Response.

* * * * *

(c) Develops emergency preparedness policies, regulations, programs, and guidelines for nuclear facilities;

* * * * *

Dated at Rockville, Maryland, this 8th day of May, 2007.

For the Nuclear Regulatory Commission.

Martin J. Virgilio,

Acting Executive Director for Operations.

[FR Doc. E7-9713 Filed 5-18-07; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28229; Directorate Identifier 2006-SW-23-AD]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model EC130 B4 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive (AD) for Eurocopter France (Eurocopter) Model EC 130 B4 helicopters, with certain twist grip assemblies installed. This proposal would require inspecting the pilot and co-pilot collective levers for proper bonding between the twist grip drive tubes and the control pinions and if debonding is present, replacing the collective levers before further flight. This proposal is prompted by one incident in which the engine remained at idle speed although the twist grip had been turned to the flight position. The actions specified by this proposed AD are intended to detect debonding between the twist grip drive tubes and the control pinions on the pilot and co-pilot collective levers to prevent loss of cockpit throttle control of the engine, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before July 20, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically;
- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically;
- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590;
- *Fax:* 202-493-2251; or
- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may get the service information identified in this proposed AD from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527.

You may examine the comments to this proposed AD in the AD docket on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Ed Cuevas, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Safety Management Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5355, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any written data, views, or arguments regarding this proposed AD. Send your comments to the address listed under the caption **ADDRESSES**. Include the docket number "FAA-2007-28229, Directorate Identifier 2006-SW-23-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed rulemaking. Using the search function of our docket Web site, you can find and read the comments to any of our dockets, including the name of the individual who sent or signed the

comment. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the docket that contains the proposed AD, any comments, and other information in person at the Docket Management System (DMS) Docket Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5227) is located at the plaza level of the Department of Transportation Nassif Building in Room PL-401 at 400 Seventh Street, SW., Washington, DC. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

The European Aviation Safety Agency (EASA) notified us that an unsafe condition may exist on Eurocopter Model EC 130 B4 helicopters, with a twist grip assembly, part number (P/N) 350A27520900, 350A27520901, 350A27520902, or 350A27520903, with a serial number below 64, installed on the pilot's side, and a twist grip assembly, P/N 350A27521201, with a serial number below 67, installed on the co-pilot's side. EASA advises that analysis of an incident that occurred during autorotation training revealed a failure of the twist grip drive tube and control pinion bonded attachment. The engine remained at idle rating although the twist grip had been turned back to the flight position. The manufacturer states that the autorotation procedure continued without damage to the helicopter, which landed safely. The failure has been attributed to non-compliant surface preparation during manufacture.

Eurocopter, an EADS Company, has issued Alert Service Bulletin EC130 No. 76A001, dated February 10, 2006, which specifies a check by use of a twist grip adjusting gauge of the bonding between the twist grip drive tube and the control pinion on both the pilot and co-pilot collective levers. If the twist grip twists under a load on the adjusting gauge of 35N, the collective lever must be replaced. EASA classified this service bulletin as mandatory and issued AD No. 2006-0079, dated April 3, 2006, to ensure the continued airworthiness of these helicopters in France.

This helicopter model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation