

ARCS2 RESET10 Audit Out Record

LOCATION	SYSTEM	P/N	S/N	CONFIG.	CONFIG.	OTHER
SMET	TRH	HMP_45D	53740006			
	WND1	05106/08234	3110358318			
	WND2	05106/08234	2839955531			
	ORG	ORG-115-DA	03317-C7			
	DAQ MET	ZENO-3200	300	V991018.00		
GNDRAD	NET	REBS Q*7.1	Q95063			
	PSP	PSP	31286F3			
	PIR	PIR	30056F3			
	IRT	KT 19 85	nr863			WD17512
	DAQ GND	ZENO-3200	034	V000112.00		
SKYRAD	PSPG	PSP	31283F3			Vent: V6-264-12
	PIRG	PIR	30084F3			Vent: V6-270-12
	UVB	501A V3	2870			
	MFRSR	MFR7-HEAD	240			
	IRT	KT 19.85	nr868			
	TRK	INTRA II				WD24187
	NIP	NIP	31352E6			
	PSPD	PSP	31277F3			Vent: V6-68
	PIRD	PIR	31389F3			Vent: V6-116
DAQ SKY	ZENO-3200	30	V991017.00			
STAND ALONE	CEIL	CT25K	P2710015			
	CEIL Comp		97-0305T			WD22794
	MWR	WVR-1100	015			WD14869
	MWR Comp		97-65L2W			WD22312
	AERI	AERI-06				
	WSI	EHT02	SYS 6A Unit 6			WD27141
	CIMEL		BNL 168			
DVAN	EMWIN					

LOCATION	SYSTEM	P/N	S/N	CONFIG.	CONFIG.	OTHER
IVAN	MPL	NA				
	MPL Contlr	MPL 004-009				
	MPL Computr	NA				
	MMCR	\r063606				
	WSI	WSI-E/06-B				
EVAN	BBSS	97-MW15G				
	BBSS Comp	IBM-2645				
	FAX machine	C2890A				
	Obsrvr Cmptr	IBM-380XD				
	EMWIN					
SAFETY	FIRST AID	2-Evan and supplies				
	CPR	1- Evan				
SPARES	4-Ventilators	V6-117	V6-128	V6-271-12	V6-127	w/base plate each
	PIR GND		30131F3			
	NIP		31351E6			
	PSP GND		30006F3			
	5 Sp. Fans					
	SMET DAQ	ZENO 3200				
	SKYRAD DAQ	ZENO 3200				
	RH Probe	HMP 45D	53740011			
	Anemometers	05106-08234	18422-44693			
	Anemometers	05106-08234	18425-44678			
OTHER						

LOCATION	SYSTEM	P/N	S/N	CONFIG.	CONFIG.	OTHER

Audit Out Philosophy

1. Check and correct if necessary the part number. Enter serial number (SN) for all instruments. They can be found on the OMS label or the instrument. Sometimes the label (OMS or manufacturer) is in a non-obvious or hard to see location, so you may have to search it out). An agency property number is also helpful, or can be used as a substitute for the SN if the agency name is included.
2. Record the final configurations of instruments as applicable (i.e. Loggers, BBSS). This may be a file, filename or printout.
3. Inventory spares (instruments, not supplies) in the storage or ARCS vans. Be sure to include non-instrument items deemed necessary to track; use your best RESET judgement. Use the part numbers on the items, or from the form; include serial number and location.
4. Enter the part number, model number (e.g. IBM 380XD), and serial number from equipment associated with listed instruments (e.g. the MWR computer). You may also enter the agency property number if no other identification can be found. This information should be entered in the OTHER column for the associated instrument.