

# ARCS RESET Audit Out Record

LOCATION	SYSTEM	Part No.	Serial No.	CONFIG.	CONFIG.
SMET	TRH	HMP45D	WO120005		
	WND1	05106/08234	31102 58342		
	WND2	05106/08234	31104 58319		
	ORG	ORG-115-DA	03327-C7		
	DAQ MET	ZENO-3200	24		
GNDRAD	NET	REBS Q*7.1	Q95065		
	PSP	PSP	30006F3		
	PIR	PIR	33057F3		
	IRT	KT 19 85	868		
	DAQ GND	ZENO-3200	038		
SKYRAD	PSPG	PSP	31277F3		
	PIRG	PIR	30056F3		
	UVB	501A V3	1900		
	MFRSR	MFR7-HEAD	0027b1da		
	IRT	KT 19.85	866		
	TRK	KZ			
	NIP	NIP	29869E6		
	PSPD	PSP(8-48)	33251		
	PIRD	PIR	33058F3		
DAQ SKY	ZENO-3200	39			
STAND ALONE	CEIL	CT25K	P0110009		
	CEIL Cmptr		78-APFK6		
	MWR	WVR-1100	16		
	MWR Cmptr		97-034H2		
	AERI				
	WSI	EHT02	Unit 3		
	CIMEL				
IVAN	MPL				

## ARCS RESET Audit Out Record

LOCATION	SYSTEM	Part No.	Serial No.	CONFIG.	CONFIG.
	MPL Controlr	1002	O22		
	MPL Computr	380XD	78-APFK9		
	MPL Laser Diode		U3332		
	MMCR		15K2 16[twpa]		
	WSI	WSI-E/06-B	Unit 3		
EVAN	BBSS	__-MW15G	T32102		
	BBSS Cmptr	380XD	78-TCM42		
	FAX Machine (Land)	HP300 Officejet	**G82-F302T		
	FAX Machine (Sat)	HP 920	MY04FE40CM		
	Obsrvr Cmptr	2635-AGU	78-TCW47		
	EMWIN				
D-Van	SAM / GOES Laptop	2635-9AU	78-CGTM5		
	Satellite Phone(Outfitters)	QUFC911925 R2K	80114		
	Fax Machine (Sat)				
SPARES	Laptop	2635-9AU	78-RLL55		
	Laptop	2635-AUG	78-BAFF3		
	PIR	PIR	31304F3		
	PSP	PSP	31284F3		
	PSP(8-48)	8-48	33243		
	Ventillator (for RADS)	VEN	V6-438-12		
	TRH Sensor	HMP45D	WO120005		
	TRH Sensor	HMP45D	WO120007		
	TRH Aspirator	43408-2	N/A		
	Zeno Datalogger	ZENO	33		
	Zeno Datalogger	ZENO	37		
	NIP	NIP	29934E6		
	NIP	NIP	31350E6		
	UVB	501A-K3	1899		

## ARCS RESET Audit Out Record

<b>LOCATION</b>	<b>SYSTEM</b>	<b>Part No.</b>	<b>Serial No.</b>	<b>CONFIG.</b>	<b>CONFIG.</b>
OTHER	SAT Phone Fax				
	Laser Power Supply				
	Voltage Source	2707A	26-1474		
	HP Laser Jet				
	Laser Writer	M2134	BCGM2134		
	Printer/Fax	C2890A	SG54462 org		
	Printer HP	C4662A	SG81MF3086		
	Voltage Source (Valhalla)	2704A	26-1474		
	MWR Power Supply				
	mfrsr stand				

### Audit Out Philosophy

1. Check the part number and correct if necessary. Enter serial number for all instruments. They can be found on the OMS label or the instrument. Sometimes the label (OMS or manufacturer) is in a non-obvious or hard to see location, so you may have to search it out). An agency property number is also needed, and should be noted in the "OTHER" column. This is important if the serial number can't be found.
2. Record the final configurations of instruments as applicable (i.e. Loggers, BBSS). This may be a file filename or printout.
3. Inventory spares (instruments, not supplies) in the storage or ARCS vans. Be sure to include non-instrument items deemed necessary to track; use your best RESET judgement. Use the part numbers on the items, or from the form; include serial number and location.
4. Enter the part number, model number (e.g. IBM 380XD), and serial number from equipment that is associated with listed instruments (e.g. the MWR computer). Use the 'OTHER' rows if necessary. You may also enter the agency property number if no other identification can be found. This information should be entered in the OTHER column for the associated instrument.

# ARCS RESET Audit Out Record

LOCATION	SYSTEM	Part No.	Serial No.	CONFIG.	CONFIG.
----------	--------	----------	------------	---------	---------

Information should be entered in the SYSTEM column for the associated instrument.

# ARCS RESET Audit Out Record

**OTHER**(property#, notes, etc.)

WD25947


WD33063

WD 12797
No AERI

--

# ARCS RESET Audit Out Record

**OTHER(property#, notes, etc.)**

WD 27984
WD 27540
WD24369,24279,277361,27440,27441,27442
WD24160,24161,24163

WD 27826 Replaced WD30551

***Wilcox Laptop****
Moved to Ivan

Los Alamos 767041
Los Alamos 767093
2TWP401
Changed out from Skyrad

# ARCS RESET Audit Out Record

**OTHER**(property#, notes, etc.)

Model 920-HP
WD-27985 Spectra Physics
YVan
Yvan
YVan
YVan
YVan

7. Enter serial number for all instruments. They can sometimes the label (OMS or manufacturer) is in a y have to search it out). An agency property number HER” column. This is important if the serial number is applicable (i.e. Loggers, BBSS). This may be a file, the storage or ARCS vans. Be sure to include non-se your best RESET judgement. Use the part 3 serial number and location. I 380XD), and serial number from equipment that is 'R computer). Use the 'OTHER' rows if necessary. 3r if no other identification can be found. This column for the associated instrument.

# ARCS RESET Audit Out Record

**OTHER**(property#, notes, etc.)