

| Maintenance Checklist for Reset Visit SV0404M | | | | | | |
|---|--|----------------------------|-------------------------|--|--|--|
| Activities | Date Accomplished/Notes | Task Time in quarter hours | | | | |
| BBSS | | | | | | |
| Assess/inspect TRH Hand Held Probe | 19-Apr-04 | 0.5 | | | | |
| Change out Digicora Battery | | | Not shipped from US yet | | | |
| H2 GENERATOR | | | | | | |
| Change out internal battery in Gas Analyzer | 19-Apr-04 | 0.5 | | | | |
| Change Oxygen cell in gas tester | 20-Apr-04 | 0.3 | Added item | | | |
| IRT | | | | | | |
| Check mirror surface coating closely | 19-Apr-04 | 1 hour | | | | |
| | Mirror looked ok. A mud wasp had built a nest inside the IRT. Time was spent | | | | | |
| MMCR | | | | | | |
| Change out fan for Radian Receiver, 12VDC | 20-Apr-04 | 0.4 | | | | |
| Change out Mux fan | 20-Apr-04 | 0.3 | Added item | | | |
| Change antenna hose | 20-Apr-04 | 1 | Added item | | | |
| Change Heater power supply | 20-Apr-04 | 0.3 | Added item | | | |
| Change TWT drier dessiccant | 20-Apr-04 | 0.2 | Added item | | | |
| UPS | | | | | | |
| Change out batteries in BBSS UPS (APC PRO 420 SC uses Vision model 1270E batteries) (Replaced with Yuasa NP7-12) | 19-Apr-04 | .5 hour | | | | |
| MPL | | | | | | |
| Change 2 x AA batteries and check settings on shutter timer | 19-Apr-04 | .2 hour | Added item | | | |
| EH&S | | | | | | |
| Change out batteries in smoke detectors | 20-Apr-04 | 1 | Added item | | | |