Standard	Operating	Procedure Interi	m Change Notice (IC	CN) Date: 8/17/05
Section 1: Description of	Change (Request	er completes) 1. Docum	ent Catalog No.: ER2005-0619	
2. SOP & Rev. No.: SOP-01.12,R0	3. ICN No.: 2	4. SOP Title: Field Site Clo	seout Checklist	
5. Description of Change:				
Update organizational titles. Update	procedure to current	template.		
Attachments Modified, Added, or F. ICN Justification: Organizational title changes and temporary.		☐ Yes	No	
	Signature on file ame, then sign.)		(Date)	8/15/05
Section 2: Evaluation and	Approval (Proie	ect Team Leader. Technical Re	eviewer, and Quality Program Project	Leader complete.)
9. Evaluation Remarks: (If none, e			, , , , , , , , , , , , , , , , , , , ,	,,
10. Project Leader: Roy Bohn	Signature (on file	(Date)	8/17/05
11. Technical Reviewer: Cheri Vidlak		on file	(Date)	8/17/05
	ame, then sign.)	Offilic	(Date)	0/17/03
11. QPPL: Dianne Wilburn	Signature on file		(5.1)	8/17/05
QP-4.2, R4	ame, then sign.)		(Date) Los Alamos National Lal Environmental Restoration	

Standard Operating Procedure (SOP) Interim Change Notice (ICN) Effective Date: 12/5/02 1 Page(s) Section 1: Description of Change (Requester completes) 1. Document Catalog No.: ER2002-0823 2. SOP & Rev. No.: 01.12, R0 3. ICN No.: 1 4. SOP Title: Field Site Closeout Checklist 5. Description of Change: Make a "global" change: change all responsibilities performed by Regulatory Deployed Person to the responsible Project Team Leader (PTL). ☐ Yes ⊠ No 6. Attachments Modified, Added, or Removed: 7. ICN Justification: Reflects new RRES-R organization and present processes 8. Requester: Roy Bohn [Signature on File [Signature on File] 12/02/02] (Print name, then sign.) (Date) Section 2: Evaluation and Approval (Project Team Leader, Technical Reviewer, and Quality Program Project Leader complete.) 9. Evaluation Remarks: (If none, enter N/A) N/A 10. Project Team Leader: Terry A. Rust [Signature on File] 12/02/02 (Print name, then sign.) (Date) 11. Technical Reviewer: Mark S. Thacker [Signature on file] 12/12/02 (Print name, then sign.) (Date) 11. QPPL: Larry Maassen 12/02/02 [Signature on File] (Print name, then sign.) (Date) **Los Alamos National Laboratory Environmental Restoration** QP-4.2, R4

Identifier: SOP-01.12	Revision: Revision 0	
Date: 8/2/1999		
Document Catalog Number: ER1999-0038		Los Alamos
Author: Roy Bo	hn	——— EST.1943 ———

Environmental Stewardship— Environmental Characterization and Remediation

Standard Operating Procedure

for Field Site Closeout Checklist

NES Approved

Responsible Division Leader: Doug Stavert	Signature & Date (1 12/14/05
Responsible Line Manager:	61.0
Alison Dorries	Signature & Date (14/05)

Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by the University of California for the United States Department of Energy under contract W-7405-ENG-36.

SOP-01.12, ICN2R0, Revision Log

Revision No.	Date	Prepared By	Description of Revisions	Affected Pages
0	8/2/99	R Bohn	New procedure	All
ICN1	12/5/02	R. Bohn	"Global"change: change all responsibilities performed by Regulatory Deployed Person to the responsible Project Team Leader (PTL)	All
ICN2	8/17/05	R. Bohn	global change with new programmatic titles, put procedure in new template.	All

Field Site Closeout Checklist

Table of Contents

1.0	PURPOSE	6
2.0	SCOPE	6
3.0	TRAINING	6
4.0	DEFINITIONS	6
5.0	RESPONSIBLE PERSONNEL	7
6.0	BACKGROUND AND PRECAUTIONS	7
7.0	EQUIPMENT	8
8.0	PROCEDURE	8
	8.1 Site Closeout Checklist Completion Responsibilities	8
	8.2 Site Closeout Sequence	8
9.0	LESSONS LEARNED	9
10.0	RECORDS	9
11.0	REFERENCES	9
12.0	ATTACHMENTS	0

List of Acronyms and Abbreviations

BMP	best management practice
ECR	Environmental Characterization and Remediation
ERS	Environmental Remediation and Surveillance
ER	Environmental Restoration
ENV	Environmental Stewardship Division
FTL	field team leader
LANL	Los Alamos National Laboratory
PL	project leader
PPE	personal protection equipment
QII	Quality Improvement and Integration Team
RPF	Records Processing Facility
SME	subject matter expert
SOP	standard operating procedure
TL	team leader
UC	University of California

Field Site Closeout Checklist

1.0 PURPOSE

This Standard Operating Procedure (SOP) describes the process for documenting completion of fieldwork at individual ER Project sites. within the Los Alamos National Laboratory (LANL or the Laboratory) Environmental Stewardship (ENV) Division - Environmental Characterization and Remediation (ECR) Group. This procedure integrates the criteria of the ENV-ECR "Quality Management Plan," hereinafter referred to as the Quality Management Plan (QMP).

2.0 SCOPE

This checklist is designed to ensure that upon demobilization from an ER Project field site all necessary field compliance activities, equipment accountability, and documentation is complete.

3.0 TRAINING

- 3.1 **Participants** shall train (e.g., read and/or classroom) to and use the current version of this SOP; contact the author of this SOP if the text is unclear.
- 3.2 **Participants** using this SOP shall document training in accordance with QP-2.2, "Personnel Training Management," using the training documentation link at the end of this document if they possess a CRYPTOCard and administrative authority to the Laboratory, employee development system (EDS), or using the Training Documentation Form located in the forms section of the ENV-ECR web page.
- 3.3 The responsible **project leader (PL)** shall monitor the proper implementation of this procedure.
- 3.4 The responsible **team leader (TL)** shall ensure that the appropriate personnel complete all applicable training assignments.
- 3.5 **Participants** may request any needed assistance with implementation of this procedure from the ECR Quality Integration and Improvement (QII) team.

4.0 DEFINITIONS

Note: Definitions specific to this procedure

- 4.1 <u>Field team leader (FTL)</u> The person responsible for the field project. This is generally the subcontractor responsible for executing the field work.
- 4.2 <u>Participant</u> An inclusive tem for any University of California (UC)/staff augmentation employee, deployed worker, or subcontractor, inclusive of project leaders, team leaders, and project personnel, who participates in activities conducted by or on behalf of the ERS Program/ECR Group. For the purposes of this SOP, this shall include any or all of the personnel listed in this section.
- 4.3 <u>Site closeout inspection</u> An on-site inspection conducted after the completion of fieldwork. This inspection is to verify that all fieldwork was completed and that all compliance issues are resolved.
- 4.4 <u>Site closeout packet</u> Documentation related to fieldwork that includes field logs, waste-management documentation, best management practices (BMP) inspection records, and sample-management records.
- 4.5 <u>Site-specific health and safety plan (SSHASP)</u> A health and safety plan that is specific to a site or ENV-ERS/ECR-related field activity that has been approved by an ENV-ECR health and safety representative. This document contains information specific to the project including scope of work, relevant history, descriptions of hazards by activity associated with the project site(s), and techniques for exposure mitigation and hazard mitigation.

5.0 RESPONSIBLE PERSONNEL

The following identifies the personnel responsible for actions in this procedure:

- Field Team Leader (FTL)
- Participants
- Project Leader (PL)

6.0 BACKGROUND AND PRECAUTIONS

- 6.1 Use this procedure in conjunction with an approved Site-Specific Health and Safety Plan (SSHASP).
- 6.2 The procedure is applicable to all subcontractor and UC project personnel who participate if field activities. Field activities included in this procedure are site investigation, remediation, and interim action projects. Field activities that do not generate waste, collect samples, or fulfill regulatory requirements (e.g., BMP inspection) are exempt from this procedure. Periodic activities such as BMP inspection can postpone site-closeout

activities until the end of the period of performance or annually whichever is shorter.

7.0 EQUIPMENT

Not applicable.

8.0 PROCEDURE

Make any deviations from this SOP in accordance with QP-5.7, "Notebook Documentation for Environmental Restoration Technical Activities" and/or SOP-01.01, "General Instructions for Field Investigations."

8.1 Site Closeout Checklist Completion Responsibilities

The following personnel are responsible for the completion of the Site Closeout Checklist and submittal of a site closeout packet:

- 8.1.1 The **PL** is responsible for the following:
 - ensuring that all field projects promptly complete the requirements of this procedure
 - inspecting the site closeout packet
 - completing and signing the Field Site Closeout Checklist (Attachment A)
- 8.1.2 The **Field Team Leader (FTL)** is responsible for the following:
 - scheduling a site closeout inspection as soon as practical following completion of planned field activities and demobilization
 - preparing and submitting the site closeout packet
 - returning the completed Field Site Closeout Checklist to the PL and the ENV-ECR Records Processing Facility (RPF)
- 8.2 Site Closeout Sequence
 - 8.2.1 Upon completion of planned field activities and demobilization activities, the **FTL** should verify that all compliance activities and records management files have been completed in accordance with the Field Site Closeout Checklist.
 - 8.2.2 Upon verification of completing the Field Site Closeout Checklist and in the preparation of a complete site closeout packet the **FTL** should contact the PL to schedule the site closeout inspection.
 - 8.2.3 The site closeout inspection should verify first that all field-related items are completed; and second that all required documentation of field activities are prepared for submittal to the RPF.

- 8.2.4 Successful site closeout inspections are documented on the Field Site Closeout Checklist which is then signed by the **PL**.
- 8.2.5 The **FTL** shall ensure distribution of the signed Field Site Closeout Checklist(s) to the PL.
- 8.2.6 The **PL** shall ensure the signed Field Site Closeout Checklist(s) is submitted to the RPF.

9.0 LESSONS LEARNED

- 9.1 Before performing work described in this SOP, **participants** should go to the Department of Energy Lessons Learned Information Services home page, located at http://www.tis.eh.doe.gov/ll/ll.html, and/or to the LANL Lessons Learned Resources web page, located at http://www.lanl.gov/projects/lessons_learned/, and search for applicable lessons.
- 9.2 During work performance and/or after the completion of work activities, **participants**, as appropriate, shall identify, document, and submit lessons learned in accordance with the LANL, Lessons Learned System located at http://www.lanl.gov/projects/lessons_learned/.

10.0 RECORDS

The **PL** shall submit the following records to the Records Processing Facility, in accordance with QP-4.4, "Record Transmittal to the Records Processing Facility":

Field Site Closeout Checklist (Attachment A)

11.0 REFERENCES

To implement properly this procedure, **participants** should become familiar with the contents of the following documents, available at http://erinternal.lanl.gov/home_links/Library_proc.shtml:

- "Quality Management Plan"
- QP-2.2, "Personnel Training Management Process"
- QP-4.4, "Record Transmittal to the Records Processing Facility"
- QP-5.7, "Notebook Documentation for Environmental Restoration Technical Activities"
- SOP-01.01, "General Instructions for Field Investigations"

12.0 ATTACHMENTS

Participants may locate all example forms associated with this procedure at http://erinternal.lanl.gov/Quality/user/forms.asp. The document user may employ documentation formats different from those attached to/named in this procedure—as long as the substituted formats in use provide, as a minimum, the information required in the official forms developed by this procedure.

Attachment A: Field Site Closeout Checklist (1 page)

<u>Using a "CRYPTOCard," click here to record "self-study" training to this procedure.</u>

If you do not possess a "CRYPTOCard" or encounter problems, contact the ENV-ECR training specialist.

Attachment A: Field Site Closeout Checklist			
1.0 Purpose This checklist is designed to ensure that when a field team demobilizes from a site all of the compliance-related items are completed.			
2.0 Site Data			
PRS/SWMU:	Date Field Activities Began:		
Subcontractor Contact:	Date Field Activities Ended:		
Subcontractor Company:	Date of Closeout Inspection:		
3.0 Checklist Items			
a) Waste Management Removed waste from site. Submitted waste-management records. Removed waste-storage area. Retrieved RFI and waste samples from labs ar Returned launderable PPE.	nd radiation-screening van.		
 b) Stormwater Compliance BMPs are in place to comply with Storm Water Pollution Prevention Plan (SWPPP). Submitted inspection records. Assigned responsibility for future BMP inspections. 			
 c) Equipment Management All field equipment was removed from site and surveyed to be free from contamination. Site trailers were inspected and are free from contamination, samples, and launderable PPE. 			
 d) Sample-Collection Summary Matched field logs with proposed sampling scheme and RFI requirements. Surveyed sample locations and forwarded data to FIMAD. 			
e) Record Management Submitted Readiness Review package. Submitted a copy of all field logs.			
f) Facility Manager Review Facility Manager approves the final site conditions.			
g) Lessons Learned Submitted memo that contains lessons learned and quality-improvement suggestions.			
4.0 Comments			
Field site closeout inspection was successfully completed.			
Project Team Leader : Date			
(Print Name, then Sign)			
	Los Alamos National Laboratory		
SOP-1.12, R0	ENV-ECR		

SOP-01.12,ICN2R0 Page 11 of 11