



Hwy. Photo #11 - View of guardrail 61 feet from the end where the rear of the motorcoach came into contact with the rail.