



Hwy. Photo #22 - Additional view of the embankment from the opposite direction (Note the area at the bottom of the photo where the fence lines intersect is the area where the motorcoach came to a final position).