



Hwy. Photo #29 - View of displaced concrete cap from guardrail support post in the area where the motorcoach contacted the rail.