

SAFETY NOTICE
TO ALL USERS OF ANTENNA PRODUCTS CORPORATION
SCE-2 SAFETY CLIMB FALL PROTECTION SYSTEMS
FEBRUARY 28, 2007, REVISED 12 MARCH, 2007

Antenna Products Corporation has discovered that under certain conditions the SCE-2 safety sleeves, part number 1000-1672-401 and 1000-0425-401, may fail to function as designed and may allow a climber to fall a distance sufficient to cause serious injuries or death. Antenna Products Corporation is issuing the following instructions to all users of the SCE-2 safety sleeves.

1. All climbers must use a maximum 6 foot long shock absorbing Y lanyard compliant with ANSI Z359.1 while climbing. The lanyard should be attached to the climber's safety harness in accordance with the lanyard manufacturers instructions and one leg of the lanyard should be connected at all times to the ladder during ascent, descent and stationary activities while on the ladder.
2. The SCE-2 sleeve should be used in the normal manner supplemented by the Y lanyard as described above.

Antenna Products Corporation is currently working to resolve the issue. When the issue is resolved and fully tested, Antenna Products Corporation will modify or replace all existing SCE-2 sleeves at no cost. Please fill out the modification / replacement form below and forward to Tammy Garland. Please contact either of the following with questions.

Contact	Phone Number	Email	Fax
Tammy Garland	940-325-3301 x240	garland@antennaproducts.com	940-325-0716
Richard Gilley	940-325-3301 x306	gilley@antennaproducts.com	940-325-0716

Antenna Products Corporation apologizes for the inconvenience caused by this situation.

Company Name _____

Address _____

City _____ State _____ Zip _____

Contact Name _____ Phone _____

Contact Email _____


Number of sleeves to return _____ Sleeve S/N _____

Return Shipping Address _____


City _____ State _____ Zip _____

Shipping Markings (if any) _____

Return To: Antenna Products Corporation
 Attn: Tammy Garland
 101 S.E. 25th Avenue
 Mineral Wells, Texas 76067



SAFE-ALERT

1. TITLE (Class, Function, Type, etc.) Sleeve, Safety, Climb Must Be Used With Shock Absorbing Y Lanyard		2. DOCUMENT NUMBER B4C-S-07-01A													
		3. DATE (DD-MMM-YY) 01-Mar-07													
4. MANUFACTURER AND ADDRESS Antenna Products Corporation 101 SE 25th Ave Mineral Wells, Texas 76067	5. PART NUMBER 1000-1672-401 and 1000-0425-401	6. NATIONAL STOCK NUMBER 4240-01-042-9688													
	7. SPECIFICATION Not Available	8. TYPE DESIGNATOR SCE-2													
	9. LOT DATE CODE START Not Available	10. LOT DATE CODE END Not Available													
11. MANUFACTURER'S POINT OF CONTACT Richard Gilley or Tammy Garland	12. CAGE 06032	13. MANUFACTURER'S FAX (940)325-0716													
14. MFR. POC PHONE (940)325-3301 x306 or x240	15. MANUFACTURER'S E-MAIL gilley@antennaproducts.com or garland@antennaproducts.com														
16. CROSS REFERENCE VENDOR Not Available	17. CROSS REFERENCE CAGE Not Available	18. CROSS REFERENCE PART Not Available													
19. PROBLEM DESCRIPTION / DISCUSSION / EFFECT Antenna Products Corp has discovered that under certain conditions the SCE-2 safety sleeves may fail to function as designed and may allow a climber to fall a distance sufficient to cause serious injuries or death.															
20. ACTION TAKEN/PLANNED Antenna Products Corp is issuing the following instructions to all users of the safety sleeves. <ol style="list-style-type: none"> All climbers must use a maximum 6 foot long shock absorbing Y lanyard compliant with ANSI Z359.1 while climbing. The lanyard should be attached to the climber's safety harness in accordance with the lanyard manufacturers instructions and one leg of the lanyard should be connected at all times to the ladder during ascent, descent and stationary activities while on the ladder. The SCE-2 sleeve should be used in the normal manner supplemented by the Y lanyard as described above. Antenna Products Corp is currently working to the resolve the issue. When the issue is resolved and fully tested, Antenna Products will modify or replace all existing SCE-2 sleeves at no cost. Please fill out the modification / replacement form below and forward to Tammy Garland. Please contact either of the following with questions. <table border="1"> <thead> <tr> <th>Contact</th> <th>Phone Number</th> <th>Email</th> <th>Fax</th> </tr> </thead> <tbody> <tr> <td>Tammy Garland</td> <td>940-325-3301 x240</td> <td>garland@antennaproducts.com</td> <td>940-325-0716</td> </tr> <tr> <td>Richard Gilley</td> <td>940-325-3301 x306</td> <td>gilley@antennaproducts.com</td> <td>940-325-0716</td> </tr> </tbody> </table>				Contact	Phone Number	Email	Fax	Tammy Garland	940-325-3301 x240	garland@antennaproducts.com	940-325-0716	Richard Gilley	940-325-3301 x306	gilley@antennaproducts.com	940-325-0716
Contact	Phone Number	Email	Fax												
Tammy Garland	940-325-3301 x240	garland@antennaproducts.com	940-325-0716												
Richard Gilley	940-325-3301 x306	gilley@antennaproducts.com	940-325-0716												
Antenna Products Corp apologizes for the inconvenience caused by this situation.															
21. DATE MFR. NOTIFIED Not Applicable	22. MANUFACTURER'S RESPONSE <input type="checkbox"/> REPLY ATTACHED Not Applicable <input type="checkbox"/> NO REPLY	23. ORIGINATOR ADDRESS/POINT OF CONTACT Antenna Products Corporation POC: Richard Gilley, 940-325-3301 x306 gilley@antennaproducts.com													
24. GIDEP REPRESENTATIVE Richard Gilley	25. SIGNATURE 	26. DATE 1 Mar 07													

SAFETY NOTICE
TO ALL USERS OF ANTENNA PRODUCTS CORPORATION
SCE-2 SAFETY CLIMB FALL PROTECTION SYSTEMS
FEBRUARY 28, 2007, REVISED 12 MARCH, 2007

Antenna Products Corporation has discovered that under certain conditions the SCE-2 safety sleeves, part number 1000-1672-401 and 1000-0425-401, may fail to function as designed and may allow a climber to fall a distance sufficient to cause serious injuries or death. Antenna Products Corporation is issuing the following instructions to all users of the SCE-2 safety sleeves.

1. All climbers must use a maximum 6 foot long shock absorbing Y lanyard compliant with ANSI Z359.1 while climbing. The lanyard should be attached to the climber's safety harness in accordance with the lanyard manufacturers instructions and one leg of the lanyard should be connected at all times to the ladder during ascent, descent and stationary activities while on the ladder.
2. The SCE-2 sleeve should be used in the normal manner supplemented by the Y lanyard as described above.

Antenna Products Corporation is currently working to the resolve the issue. When the issue is resolved and fully tested, Antenna Products Corporation will modify or replace all existing SCE-2 sleeves at no cost. Please fill out the modification / replacement form below and forward to Tammy Garland. Please contact either of the following with questions.

Contact	Phone Number	Email	Fax
Tammy Garland	940-325-3301 x240	garland@antennaproducts.com	940-325-0716
Richard Gilley	940-325-3301 x306	gilley@antennaproducts.com	940-325-0716

Antenna Products Corporation apologizes for the inconvenience caused by this situation.

Company Name _____

Address _____

City _____ State _____ Zip _____

Contact Name _____ Phone _____

Contact Email _____

Number of sleeves to return _____ Sleeve S/N _____

Return Shipping Address _____

City _____ State _____ Zip _____

Shipping Markings (if any) _____

Return To: Antenna Products Corporation
 Attn: Tammy Garland
 101 S.E. 25th Avenue
 Mineral Wells, Texas 76067

