

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 47

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 47

---

**Facility Name: Quad Cities 2 Docket (050- 00265)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	S - Surveillance	050-00265/2006-006
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 4</b>			
<hr/>			
<b>Oversight / IR</b>			
130 - Inadequate suprevision / command and control	E - Electrical	S - Surveillance	050-00265/2006-003
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 2</b>			
<hr/>			
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00265/2006-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00265/2006-009
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 9</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00265/2006-006
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
142 - Operating experience (OE) review LTA	O - Operations	O - Control Room Ops	050-00265/2006-012
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-006
146 - Evaluation LTA	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
146 - Evaluation LTA	G - Engineering	G - Design	050-00265/2006-005
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00265/2006-009
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
<b>Number of Items for this Docket: 9</b>			
<b>Percent of Total for this Docket: 19</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
184 - Tag outs LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00265/2006-003

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 47

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 47

---

**Facility Name: Quad Cities 2 Docket (050- 00265)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00265/2006-003
185 - Procedural adherence LTA	E - Electrical	S - Surveillance	050-00265/2006-003
185 - Procedural adherence LTA	I - Instrumentation & Control	S - Surveillance	050-00265/2006-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-006
185 - Procedural adherence LTA	M - Mechanical	S - Surveillance	050-00265/2006-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00265/2006-003
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
187 - Action implementation LTA	E - Electrical	G - Design	050-00265/2006-003
187 - Action implementation LTA	E - Electrical	G - Design	050-00265/2006-003
187 - Action implementation LTA	E - Electrical	G - Design	050-00265/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00265/2006-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00265/2006-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00265/2006-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00265/2006-012
187 - Action implementation LTA	G - Engineering	Q - Fire Protection	050-00265/2006-002
187 - Action implementation LTA	G - Engineering	Q - Fire Protection	050-00265/2006-002
187 - Action implementation LTA	G - Engineering	S - Surveillance	050-00265/2006-003
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-005
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-003
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00265/2006-002
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00265/2006-003
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00265/2006-005
190 - Failure to stop work / non-conservative decision making	M - Mechanical	S - Surveillance	050-00265/2006-003
196 - Independent verification / plant tours LTA	G - Engineering	G - Design	050-00265/2006-009
196 - Independent verification / plant tours LTA	M - Mechanical	M - Maintenance / Repair	050-00265/2006-009

Number of Items for this Docket: 31

Percent of Total for this Docket: 66

---

**Total Items for this Docket: 47**


---