

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00482/2008-006
Number of Items for this Docket: 2			
Percent of Total for this Docket: 2			

Procedures & Reference Document / IR

111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00482/2008-003
111 - Procedure / reference document technical content	Y - Shipping / transportation	Y - Shipping / transportatic	050-00482/2008-009
113 - Procedure / reference document development and maintenance L	P - Procedure Writers	P - Procedure Dev	050-00482/2008-003
113 - Procedure / reference document development and maintenance L	Y - Shipping / transportation	Y - Shipping / transportatic	050-00482/2008-009
Number of Items for this Docket: 9			
Percent of Total for this Docket: 11			

Problem Identification & Resolution / IR

140 - Problem not completely or accurately identified	E - Electrical	S - Surveillance	050-00482/2008-006
140 - Problem not completely or accurately identified	G - Engineering	G - Design	050-00482/2008-006
142 - Operating experience (OE) review LTA	F - Fuel Handling	R - Refueling	050-00482/2008-006
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
142 - Operating experience (OE) review LTA	O - Operations	O - Control Room Ops	050-00482/2008-006
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00482/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00482/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00482/2008-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00482/2008-003
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-005

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / IR			
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00482/2008-006
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00482/2007-005
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00482/2008-006
147 - Individual corrective action LTA	O - Operations	O - Control Room Ops	050-00482/2008-006
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00482/2008-006
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
149 - No action planned	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
150 - Programmatic deficiency	G - Engineering	G - Design	050-00482/2008-006
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
Number of Items for this Docket: 29			
Percent of Total for this Docket: 35			

Work Planning & Practices / IR

182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-005
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
185 - Procedural adherence LTA	E - Electrical	R - Refueling	050-00482/2008-003
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00482/2008-006
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00482/2008-003
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00482/2008-003
185 - Procedural adherence LTA	M - Mechanical	F - Modification	050-00482/2008-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-005
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00482/2008-006
186 - Failure to take action / meet requirements	E - Electrical	R - Refueling	050-00482/2008-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00482/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00482/2008-006

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00482/2008-006
186 - Failure to take action / meet requirements	Y - Shipping / transportation	Y - Shipping / transportatic	050-00482/2008-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2008-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2008-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2008-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2008-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2008-006
187 - Action implementation LTA	G - Engineering	G - Design	050-00482/2008-006
187 - Action implementation LTA	Y - Shipping / transportation	Y - Shipping / transportatic	050-00482/2008-009
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00482/2007-005
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00482/2008-006
190 - Failure to stop work / non-conservative decision making	M - Mechanical	F - Modification	050-00482/2008-003
190 - Failure to stop work / non-conservative decision making	M - Mechanical	R - Refueling	050-00482/2008-003
193 - Non-conservative action	E - Electrical	R - Refueling	050-00482/2008-003
193 - Non-conservative action	F - Fuel Handling	R - Refueling	050-00482/2008-003
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2007-005
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-003
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00482/2008-006
196 - Independent verification / plant tours LTA	G - Engineering	G - Design	050-00482/2008-003
196 - Independent verification / plant tours LTA	G - Engineering	G - Design	050-00482/2008-003
Number of Items for this Docket: 35			
Percent of Total for this Docket: 43			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00482/2008-008-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 1			
Problem Identification & Resolution / LER			
142 - Operating experience (OE) review LTA	O - Operations	O - Control Room Ops	050-00482/2008-008-00
146 - Evaluation LTA	O - Operations	O - Control Room Ops	050-00482/2008-008-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 2			

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Wolf Creek 1 Docket (050- 00482)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / LER			
180 - Scheduling and planning LTA	M - Mechanical	T - Testing	050-00482/2008-006-00
187 - Action implementation LTA	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00482/2008-006-00
188 - Work practice or craft skill LTA	E - Electrical	T - Testing	050-00482/2008-003-00
197 - Self-check LTA	E - Electrical	T - Testing	050-00482/2008-004-00
Number of Items for this Docket: 4			
Percent of Total for this Docket: 5			

Total Items for this Docket: 82
