



Federal Aviation Administration

SAFETY ALERT

Date: August 06, 2012
To: Users of the Coded Instrument Flight Procedures (CIFP)
From: National Aeronautical Navigation Services (AeroNav Services)
Subject: SMA (ST MARYS) NDB Coordinate/Station Declination Change

There is an error in the **26 JUL, 2012** and **23 AUG, 2012** edition of the CIFP (**1208** and **1209**)

The CIFP-published latitude and longitude (5.36, 5.37) and Station Declination (5.66) for the Navaid (DB record) SMA (St Mary's NDB) are in error and should be as follows:

Latitude and Longitude: N62033380W163165480 vice N62033010W163172980
Station Declination: E0120 vice E0150

The following Airways have segments whose courses will also be impacted by this change:

J179, A6, B27, G6, G15, V459, V496 and B932

A follow on alert will identify these changes.

This error will be corrected in the 1210 edition of the CIFP.