

FAA Airports

Errata Sheet for Advisory Circular 150/5370-2F, Operational Safety on Airports During Construction Last Update: February 3, 2012

This errata sheet logs content and/or coding errors identified after the AC was signed on September 29, 2011. These errors have been corrected in the PDF version of the AC available on the FAA website.

#	Description of Correction	Location	Rationale	Date Error Corrected
1	Replaced Figure 2-2.	Page 20.	Original drawing showed runway centerline in yellow. New drawing shows correct runway centerline drawn in white.	10/14/2011
2	The following formatting errors are fixed: Paragraphs 218.b.(1)(e)(i-iv) changed to paragraphs 218.b.(2-5) Paragraph 218.b.(1)(f) changed to paragraph 218.c.	Page 21	Paragraphs 218.b.(1)(e)(i-v) and 218.b.(1)(f) are shown at the wrong level.	2/6/2012