

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 20

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 20

Facility Name: Hatch 2 Docket (050- 00366)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	I - Instrumentation & Control	T - Testing	050-00366/2006-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	T - Testing	050-00366/2006-007
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	D - Emergency Planning	D - Emergency Drill	050-00366/2006-013
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00366/2006-006
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00366/2006-007
146 - Evaluation LTA	E - Electrical	M - Maintenance / Repair	050-00366/2006-007
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00366/2006-002
Number of Items for this Docket: 4			
Percent of Total for this Docket: 20			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	L - Licensing / regulatory affairs	A - Administrative	050-00366/2006-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00366/2006-007
186 - Failure to take action / meet requirements	I - Instrumentation & Control	T - Testing	050-00366/2006-006
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00366/2006-002
190 - Failure to stop work / non-conservative decision making	E - Electrical	M - Maintenance / Repair	050-00366/2006-007
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00366/2006-002
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00366/2006-006
Number of Items for this Docket: 7			
Percent of Total for this Docket: 35			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	I - Instrumentation & Control	C - Calibration	050-00366/2006-002-00
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00366/2006-003-00
111 - Procedure / reference document technical content	O - Operations	B - Bal of Plant Ops	050-00366/2006-004-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 20

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 20

Facility Name: Hatch 2 Docket (050- 00366)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00366/2006-001-00
Number of Items for this Docket: 4			
Percent of Total for this Docket: 20			
Work Planning & Practices / LER			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00366/2006-003-00
189 - Recognition of adverse condition / questioning attitude LTA	L - Licensing / regulatory affairs	A - Administrative	050-00366/2006-003-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 10			
Total Items for this Docket: 20			
