

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 20

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 20

---

**Facility Name: Surry 1 Docket (050- 00280)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	T - Testing	050-00280/2006-003
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00280/2006-003
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 10</b>			
<hr/>			
<b>Oversight / IR</b>			
130 - Inadequate suprevision / command and control	M - Mechanical	M - Maintenance / Repair	050-00280/2006-003
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 5</b>			
<hr/>			
<b>Procedures &amp; Reference Document / IR</b>			
110 - No procedure / reference documents	I - Instrumentation & Control	T - Testing	050-00280/2006-003
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00280/2006-009
111 - Procedure / reference document technical content	I - Instrumentation & Control	G - Design	050-00280/2006-006
111 - Procedure / reference document technical content	I - Instrumentation & Control	T - Testing	050-00280/2005-005
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00280/2006-002
<b>Number of Items for this Docket: 5</b>			
<b>Percent of Total for this Docket: 25</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00280/2006-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00280/2006-002
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 10</b>			
<hr/>			
<b>Training / IR</b>			
101 - Training process problem	D - Emergency Planning	D - Emergency Drill	050-00280/2006-008
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 5</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00280/2006-009
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00280/2006-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00280/2006-004
187 - Action implementation LTA	I - Instrumentation & Control	G - Design	050-00280/2006-006
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00280/2005-005
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	D - Emergency Drill	050-00280/2006-008

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 20**  
**National Average: 43**  
**2x National Average: 86**  
**National Median: 24**  
**Average for Selected Dockets: 20**

**Facility Name: Surry 1 Docket (050- 00280)**

**Details**

**Work Planning & Practices / IR**

190 - Failure to stop work / non-conservative decision making

197 - Self-check LTA

197 - Self-check LTA

**Department**

D - Emergency Planning

F - Fuel Handling

O - Operations

**Work Type**

Q - Fire Protection

R - Refueling

B - Bal of Plant Ops

**Docket/Report**

050-00280/2006-009

050-00280/2006-003

050-00280/2005-005

**Number of Items for this Docket: 9**

**Percent of Total for this Docket: 45**

**Total Items for this Docket: 20**