

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Turkey Point 3 Docket (050- 00250)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
Fitness for Duty / IR			
125 - Work hour control	O - Operations	O - Control Room Ops	050-00250/2008-002
125 - Work hour control	O - Operations	O - Control Room Ops	050-00250/2008-002
127 - Circadian factors / individual difference	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
Number of Items for this Docket: 3			
Percent of Total for this Docket: 7			
Human-System Interface & Environmnt / IR			
171 - Simulator fidelity LTA	T - Training	N - Training	050-00250/2008-002
171 - Simulator fidelity LTA	T - Training	N - Training	050-00250/2008-002
171 - Simulator fidelity LTA	T - Training	N - Training	050-00250/2008-002
Number of Items for this Docket: 3			
Percent of Total for this Docket: 7			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
Number of Items for this Docket: 2			
Percent of Total for this Docket: 4			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00250/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00250/2007-009
146 - Evaluation LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00250/2007-009
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2007-009
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2007-009
147 - Individual corrective action LTA	G - Engineering	G - Design	050-00250/2008-003
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2007-005
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00250/2008-003
150 - Programmatic deficiency	X - Site-wide	X - Site-wide	050-00250/2007-009
Number of Items for this Docket: 9			
Percent of Total for this Docket: 20			

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Turkey Point 3 Docket (050- 00250)

Details	Department	Work Type	Docket/Report
Training / IR			
102 - Individual knowledge LTA	G - Engineering	G - Design	050-00250/2007-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
<hr/>			
Work Planning & Practices / IR			
180 - Scheduling and planning LTA	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
180 - Scheduling and planning LTA	O - Operations	O - Control Room Ops	050-00250/2008-002
180 - Scheduling and planning LTA	O - Operations	O - Control Room Ops	050-00250/2008-002
180 - Scheduling and planning LTA	O - Operations	O - Control Room Ops	050-00250/2008-002
180 - Scheduling and planning LTA	O - Operations	O - Control Room Ops	050-00250/2008-002
181 - Inadequate staffing / task allocation	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00250/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00250/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00250/2008-002
181 - Inadequate staffing / task allocation	O - Operations	O - Control Room Ops	050-00250/2008-002
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2007-005
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2008-003
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00250/2008-003
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2008-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00250/2007-005
186 - Failure to take action / meet requirements	A - Administrative Support	A - Administrative	050-00250/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00250/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00250/2007-005
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00250/2007-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00250/2008-003
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00250/2007-005
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00250/2007-005
Number of Items for this Docket: 23			
Percent of Total for this Docket: 50			

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Turkey Point 3 Docket (050- 00250)

Details	Department	Work Type	Docket/Report
Communication / LER			
161 - Communication LTA	O - Operations	O - Control Room Ops	050-00250/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00250/2008-001-00
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00250/2008-003-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 4			
Work Planning & Practices / LER			
185 - Procedural adherence LTA	G - Engineering	V - Troubleshooting	050-00250/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
Total Items for this Docket: 46			
