

NAVAID Naming Protocol – The outgoing Executive Director briefed on the status of this agenda item. Currently this is being worked by the Operations Steering group with action items briefed out through ATSAP briefing sheet dated 7/29/2010.

Action:

✧ Issuance of a NOTICE and associated DCP to clarify the descriptions contained in 7110.65, Chapter 2, Section 5 and clarify Chapter 4, Section 3. The required documentations is in development. Update: DCPs are going out for comment, and the OSG is looking at between 90 and 100 days from mid October complete process and generate Notice.

✧ Tasking the Service Centers to study the magnitude of the problem and estimate costs for modifications. The estimate was due by September 30, 2010. No current update.

✧ Examine whether the guidance in 7400.2 concerning NAVAID naming requires modification concerning the co-locations of NAVAIDs on airports and the allowable distances. No current update.