



New Jersey



American Recovery and Reinvestment Act

35 DoD Projects (\$ 13.7M) Completed or Under Way by August 31, 2009

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repairs to Dams- Picatinny Lake & L Denmark	Army	Picatinny Arsenal	2,300
B3150 Repair Roof	Army	Picatinny Arsenal	1,800
B-119 Renovate Garrison Staff Offices	Army	Picatinny Arsenal	933
Repair Reilly Rd Pavement	Army	Picatinny Arsenal	675
Chiller Replacements Building 1, 92 and 94	Army	Picatinny Arsenal	500
Inspect and Design Water Distribution replacement system	Army	Picatinny Arsenal	450
Repair Road (3rd Ave)	Army	Picatinny Arsenal	450
Siding Replacement	Army	Picatinny Arsenal	450
B-12 Level Parking Lot	Army	Picatinny Arsenal	417
Renovate Old Firehouse to Outdoor Rec Facility	Army	Picatinny Arsenal	400
Replace Existing Service Water Line	Army	Picatinny Arsenal	400
B-173 Replace Air-conditioning	Army	Picatinny Arsenal	300

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Fire Protection - Repair Sprinkler/Deluge Systems, Various Buildings	Army	Picatinny Arsenal	226
Renovate Unit Ops Building 13 - Finishes, Doors, Windows, Elect, Plumbing, HVAC	Army	Picatinny Arsenal	200
Repair Street Lights	Army	Picatinny Arsenal	150
Chiller Replacements	Army	Picatinny Arsenal	150
B351 Repair & Paint Exterior of Building	Army	Picatinny Arsenal	100
B-3111 Repair Roof	Army	Picatinny Arsenal	80
B3329 Repair Roof	Army	Picatinny Arsenal	80
Building 455 Repair Roof	Army	Picatinny Arsenal	80
A/E Waterline Design	Army	Picatinny Arsenal	75
B3106 Repair Roof	Army	Picatinny Arsenal	75
B-617 Repair Roof	Army	Picatinny Arsenal	60
Expand/Upgrade Telemetry & industrial control Sys	Army	Picatinny Arsenal	50
Hardwire Telemetry System	Army	Picatinny Arsenal	50
B68 Replace Roof	Army	Picatinny Arsenal	35
Repair/Replace Electric Heaters	Army	Picatinny Arsenal	29

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Roof Repair	Army	Picatiny Arsenal	25
Interior/Exterior Repairs, Museum, Building 6501	Army Reserve	Fort Dix	750
Repair Airfield Concrete Main Ramp Twy Papa to Fox	Air Force	McGuire AFB	1,368
Addition to 463I Vehicle Maintenance Facility, B1750 R/M	Air Force	McGuire AFB	743
Repair Airfield Alpha Ramp Shoulders S/R	Air Force	McGuire AFB	118
Repair Building 2901 for Air Base Wing Occupancy Rm	Air Force	McGuire AFB	97
Repair Fire Detection Systems, Multiple Facilities.	Air Force	McGuire AFB	54
Relocate Smoke / Fire Detectors, VQ 2784 R/M	Air Force	McGuire AFB	29