




NTSB National Transportation Safety Board

Professionalism in Aviation

Robert L. Sumwalt
NTSB Board Member







NTSB is an independent federal agency, charged by Congress to investigate transportation accidents, determine probable cause, and issue safety recommendations.



NTSB





Facilities

- Headquartered in Washington, DC
- 9 Regional Offices
- NTSB Training Center



NTSB



Most Wanted List



Critical changes needed to reduce transportation accidents and save lives

National
Transportation
Safety Board

NTSB






**Professionalism:
Maintaining the
right attitude**

NTSB



June 4, 2007



What the investigation found

Captain/chief pilot/check airman

- had prior certificate revocation
- routinely failed to comply with procedures and regulations
- falsified training records

NTSB Finding

- “The pilots’ lack of discipline, in-depth systems knowledge, and adherence to procedures contributed to their inability to cope with anomalies experienced during the accident flight.”



Aviation-safety.net © Paul Kanagie / PHLAIRLINE.COM

Owatonna, MN
July 31, 2008
8 fatalities



Accident sequence

- F/O called FBO 3 minutes before touchdown
- Wet runway, 8 knot tailwind
- After touchdown, Captain delayed 7 seconds before deploying Lift Dump
- 17 seconds after touchdown, captain initiated go-around/
takeoff attempt
 - Appx. 1200 feet from runway end
 - Appx. 75 – 80 knots
- Collided with localizer antenna



NTSB finding

- “The captain allowed an atmosphere in the cockpit ... including [lack of] sterile cockpit adherence, and this atmosphere permitted inadequate briefing of the approach and monitoring of the current weather conditions; ... inappropriate conversation; nonstandard terminology; and a lack of checklist discipline throughout the descent and approach phases of the flight.”

Colgan Air flight 3407

- February 12, 2009
- 10:17 pm Eastern Standard Time
- Colgan Air, Inc.
 - Operated as Continental Connection
- Bombardier DHC-8-400
- On approach to Buffalo, New York
- 50 fatalities
 - 2 pilots
 - 2 flight attendants
 - 45 passengers
 - 1 home resident killed

History of flight

- Crew engaged in almost continuous conversation throughout flight
 - Conversation mostly extraneous to flight operations
- Conversation preempted timely performance of flight-related duties
 - Approach briefing, descent checklist, approach checklist



History of flight

- Approximately 3 miles from outer marker:
 - power was reduced to slow for approach
 - gear extended
 - props to max RPM
- Airspeed decreased 50 kts in 21 seconds

Stall, Upset, Loss of Control

- Stick shaker (stall warning) activated at 131 knots
- Autopilot disconnected
- Captain reacted with “startle and confusion”
- Captain pulled nose to 19 degrees nose up pitch
- Stall, extreme roll
- Stick pusher activated 3 times
 - countered by captain’s actions of pulling
- Loss of control

HOT-2: gear's down.

HOT-1: flaps fifteen before landing checklist.

HOT-2: uhhh.



National Transportation Safety Board *Board Meeting*

22:16:27

130 knots **2280** feet **Shaker ON** Pusher **OFF** Power Condition Flap



Heading **247**°



Pedal **L** **R**



Auto Pilot **OFF** Gear **DOWN**



NTSB

National Transportation Safety Board

Office of Research and Engineering

Flightpath

Loss of Control on Approach
Colgan Air, Inc., Operating as
Continental Connection Flight 3407
Bombardier DHC-8-400, N200WQ

Clarence Center, New York

February 12, 2009

DCA09MA027

Board Meeting





Major Areas of Focus



Airspeed
Selection

Cockpit
Discipline

Crew Reaction
to Stall Warning
and Stall



NTSB



NTSB Finding

- The captain's failure to effectively manage the flight
 - enabled conversation that delayed checklist completion and conflicted with sterile cockpit procedures, and
 - created an environment that impeded timely error detection.

Pinnacle Airlines Flight 3701

Jefferson City, Missouri



- October 14, 2004
- Bombardier CL-600-2B19
- Repositioning flight
- Both flight crewmembers killed

What the investigation discovered

- Intentional activation of stall warning
- Swapping crew seats
- Rudder mishandling
- Climb to FL 410
 - “have a little fun”
- Automation mismanagement
- Airspeed loss, stall, loss of control, double engine failure
- Did not fully disclose real problem with ATC

NTSB's Probable Cause

- “the pilots’ unprofessional behavior, deviation from standard operating procedures, and poor airmanship, which resulted in an in-flight emergency from which they were unable to recover...”



Teterboro, NJ

Feb 2, 2005



NTSB



NTSB finding

- “The pilots’ failure to ensure that the airplane’s weight and center of gravity were within approved takeoff limits was symptomatic of poor airmanship and a broader pattern of deficiencies in their CRM skills (specifically in the areas of leadership, workload management, communications/briefings, and crew coordination) ...”

Midair collision over Hudson River

- August 8, 2009
- 9 fatalities





NTSB

National Transportation Safety Board

Office of Research and Engineering

Flight Path Animation

Midair Collision Over Hudson River,
Piper PA-32R-300, N71MC, and
Eurocopter AS350BA, N401LH,

Near Hoboken, New Jersey

August 8, 2009

ERA09MA447AB



Corporate Airlines dba American Connection Flight 5966 Kirksville, Missouri



- October 19, 2004
- BAE J-32 (Jetstream)
- Crashed into trees on nighttime non-precision instrument approach
- 13 fatalities
- 2 serious injuries

NTSB Finding

- “The pilots’ nonessential conversation below 10,000 feet MSL ... reflected a demeanor and cockpit environment that fostered deviation from established standard procedures, crew resource management disciplines, division of duties, and professionalism, reducing the margin of safety well below acceptable limits ...”

Charleston, WV January 19, 2010



Approximate location
of stopped aircraft.

Probable cause:

- “...the flight crewmembers’ unprofessional behavior, including their non-adherence to sterile cockpit procedures by engaging in non-pertinent conversation, which distracted them from their primary flight-related duties and led to their failure to correctly set and verify the flaps.”



Comair Airlines Flight 5191

Lexington, Kentucky


- Bombardier CRJ
- 49 Fatalities
- First officer severely injured
- Wrong runway takeoff





Crew Actions

- Setting tone during preflight
 - Casual and relaxed
- Noncompliance with sterile cockpit rule
 - 40 of the 150 seconds during taxi were violations of sterile cockpit rule
- Distraction likely contributed to loss of positional awareness



NTSB Finding

- “The flight crew’s noncompliance with standard operating procedures, including the captain’s abbreviated taxi briefing and both pilots’ nonpertinent conversation, most likely created an atmosphere in the cockpit that enabled the crew’s errors.”

A fine line

- “There is a fine line separating a relaxed and easy atmosphere in a cockpit from a lax one where distractions can result in critical failures.”
- “Professionalism may be described as knowing the difference between the two.”
 - Honorable John K. Lauber





A/C 7271
N337AS

NAME: [Redacted]
 TITLE: [Redacted]
 PHONE: [Redacted]
 FAX: [Redacted]
 ADDRESS: [Redacted]
 CITY: [Redacted]
 STATE: [Redacted]
 ZIP: [Redacted]

THIS AIRCRAFT IS CERTIFIED FOR RVSM OPERATIONS

THIS AIRCRAFT IS CERTIFIED FOR CAT II & III OPERATIONS

44,000 LBS			
MAX. WT. OF PASSENGERS			
FLAPS UP	FLAPS 10	FLAPS 25	FLAPS 30
123	123	123	123
124	124	124	124
125	125	125	125
126	126	126	126
127	127	127	127
128	128	128	128
129	129	129	129
130	130	130	130

A Few Tips

to Avoid This





NTSB



NTSB

Negative Publicity Avoidance

**“You never know on which
flight your career will be
judged.”**



NTSB



SPORTS FINAL

DETROIT STUNS 49ERS 27-24

1,10C
LIONS WERE WINLESS
▶ REFS UNDER REVIEW, 1C
▶ NFL REPORT, 1,10,13C



ANDRUW JONES IS USA TODAY'S MINOR LEAGUE PLAYER OF THE YEAR

By Andrew Rickoff
ANDRUW JONES: 25 HRs and 100 RBI, 1C
OUTFIELDER ANOTHER STAR IN ATLANTA CONSTELLATION, 1C

NO. 1 IN THE USA . . . FIRST IN DAILY READERS

HOME SALES HIT HIGHEST POINT IN 15 MONTHS

1B
EVEN IF SURGE FALTERS, ECONOMY WILL GET BOOST

NEW FILMS FEATURE WOMEN AND ISSUES THEY FACE TOGETHER

1D
SISTERHOOD TO OUTSHINE SHOWGIRLS, DRAG QUEENS, 1D

TUESDAY, SEPTEMBER 26, 1995

NEWSLINE

A QUICK READ ON THE NEWS

WALL STREET: Dow Jones industrial average rises 5.78 points to 4769.93; Nasdaq index falls 7.24 to 1046.15; 30-year Treasury bond yield remains at 6.58%. 1,3B.

CHILD BURIED: Stephanie Kuhen, 3, is buried; she died when the car she was in was hit by gunfire on Los Angeles dead-end street. Fourth suspect arrested. 4A.

BALANCING ACT: Clinton administration walks fine line to balance human rights commitment with pledge to make job protection heart of foreign relations. 9A.

NEW AIRLINE: British entrepreneur Sir Freddie Laker and a Texas oilman plan to launch U.S.-based trans-Atlantic airline with flights from Florida to Britain. 1B.

CHESS BATTLE: Challenger Viswanathan Anand, left, beats reigning champ Garry Kasparov in the ninth game, breaking series of draws and recording the first win in Professional Chess Association world championship in New York. 13C.



DELANY DIES: Bessie Delany, second black female dentist in New York, subject of

Your name here (?)

FIRST IN A 3-PART SERIES

WARNING: PILOT ERROR


How regional airlines failed to heed warning signals about pilots who didn't belong in the cockpit

Dead Calif. mont

By Mimi Ha USA TODAY

Former dental can said Mond porters are third nation Such a p dramatic e presidential Perot, on Live, said t dence Party voters who they don't f Democrats "It will no special inte who got 199 he ran in owned by (t He told K economy, "t that have to Perot d

ETERANS



Pilots' acts might have led to crash

■ Tail section of doomed jet found on ocean floor

By ERIC MALNIC, MATT SURMAN and MITCHELL LANDSBERG
Los Angeles Times

PORT HUENEME, Calif. — Investigators are considering whether the pilots of Alaska Airlines Flight 261 unwittingly triggered their violent plunge into the Pacific Ocean by following prescribed procedures for an emergency landing, air safety officials said Thursday.

Late Thursday searchers found the tail of the jet after recovering the flight data recorder earlier in the day.

Underwater robots exploring the ocean floor found where the wreckage came to rest after the MD-83

ies, some of which are believed trapped under the debris.

National Transportation Safety Board officials raised the question about the pilots' actions after listening to a recording of the final 30 minutes that was contained in a cockpit voice recorder retrieved late Wednesday.

One NTSB official, speaking on condition of anonymity, said the investigation into the crash is increasingly focusing on the pilots' actions during their preparation for an emergency landing at Los Angeles International Airport.

In hindsight, investigators say, it appears possible that a by-the-book response to the mechanical problem reported by the pilots — a "horizontal stabilizer jam" — could have sent the plane into its wild, corkscrewing descent into the sea.





NTSB

Take the Most Conservative Approach


What to do?

Take the most conservative approach

De-ice?

Divert?

Add more fuel?



Don't de-ice

Continue?

Risk min fuel
landing?



NTSB


SOP Adherence

What accident data show

Accident Causal Factors

Hull-loss Accidents over 10 Year Period

Percentage of Accidents




Source: Boeing study of accident prevention strategies

What accident data show

Accident Causal Factors

Hull-loss Accidents over 10 Year Period

Percentage of Accidents



Source: Boeing study of accident prevention strategies

How SOPs relate to error

- LOSA data: crews that intentionally deviate from SOPs are approximately three times more likely to commit additional errors with consequential results.
- “Normalization of Deviance”



NTSB

Be Professional

What is a professional?

- A mindset
 - Precise checklist usage
 - Precise callouts
 - Precise compliance with SOPs and regulations
 - Staying abreast and current with knowledge and skills
 - The ability and willingness to say “I don’t know” or “I am wrong”

Professionalism

Doing the right things,
even when no one is watching.



NTSB



NTSB

NTSB

