POST TEST

- 1. Common causes of cave-ins are;
 - A. Poor planning
 - B. Misjudgment of soil type
 - C. Defective protective systems
 - D. Failure to adjust for changing conditions
 - E. All the above
- 2. Excavation standard applies to;
 - A. Excavations
 - B. trenches
 - C. surface encumbrances
 - D. protective systems
 - E. All the above

3. Timber and aluminum hydraulic are ______ systems.

- A. Shoring
- B. Ramp
- C. Hazardous
- D. Access
- 4. A hazardous atmosphere can be;
 - A. Flammable
 - B. Poisonous
 - C. Toxic
 - D. Irritating
 - E. All the above
- 5. Surface encumbrances that are hazardous to employees shall be ______ as necessary to safeguard employees.
 - A. Added
 - B. Removed or supported
 - C. Built in
 - D. Blocked

6. Structural ramps used by employees shall be designed by _____

- A. Safety officer
- B. Laborer
- C. Competent person
- D. Operator
- 7. Oxygen deficient atmosphere are problems in trenches when the oxygen content falls below;
 - A. 12.5% B. 30.5%
 - C. 19.5%
 - D. 25.5%

8. Water removal operations shall be monitored by a _____

- A. Competent person
- B. Safety person
- C. Water man
- D. Flag person
- 9. Competent persons shall take prompt corrective measures when surroundings are ______ to employees?
 - A. Hazardous
 - B. Unsanitary
 - C. Dangerous
 - D. All the above
- 10. Employees are ______ in shields when being installed, removed or moved vertically.
 - A. Not permitted
 - B. Permitted
- 11. Type A soils are fissured, subject to vibration, previously disturbed?
 - A. True B. False

- 12. A visual test and a ______ test shall be done to determine soil classification?
 - A. Standard
 - B. Manual
 - C. Perk
 - D. Legal

13. Cohesive soils have a high _____ content?

- A. Clay
- B. Rock
- C. Sand
- D. Gravel

14. ______ is caused by a downward pressure created by weight of adjoining soil or equipment?

- A. Heaving or squeezing
- B. Toppling
- C. Boiling
- 15. Timber can be used to shore trenches up to ______ feet in Depth without a registered engineer's approval?
 - A. 10
 - B. 20
 - C. 30
 - D. 40

University of Maryland Fire and Rescue Institute Susan Harwood Grant SH-16582-07

Post – Test Answers

- 1) E
- 2) E
- 3) C
- 4) E
- 5) B
- 6) C
- 7) C
- 8) A
- 9) D
- í 10) A
- 11) B
- 11) D
- 12) B
- 13) A
- 14) A
- 15) B