



Improvements at Locations 1 & 2

Location 2a Widen the Seminary Road westbound approach and gore area from the rotary to the Mark Center Drive intersection from one to two lanes. Restripe the westbound Seminary Road flyover to allow one through lane on Seminary and one left turn lane into Mark Center. Provide a physical separation between the two lanes from the rotary and the left turn lane at Mark Center Drive.

Location 2b Widen Seminary Road to provide a dedicated right turn lane from westbound Seminary Road to Southern Towers.