Brookhaven National Laboratory – Photon Sciences - National Synchrotron Light Source						
Beamline Hazard Analysis - Beamline X15B						
LS-BHA-X15B	Revision:	02	Effective: 10/17/11	Page 1 of 1		
The fellowing to de	· · · ·					

The following tasks are included in the beamline safety review. Any operations not listed here, or performed by others than those listed, need additional review by ES&H personnel and/or beamline personnel.

Prepared By:	P. Northrup	Approved By:	Lori Stiegler

Tasks / Equipment	Performed	by:	Controls		
	Beamline Staff	Users			
Inert compressed gas	Y	Y	 Compressed gas training – TQ-COMPGAS1 or NSLS User training Transport cylinders using a cylinder cart Properly secure cylinders Wear safety glasses with side shields while connecting lines Leak check gas lines 		
Toxic compressed gases	Y	Y	 Compressed gas training – TQ-COMPGAS1 or NSLS User training Transport cylinders using a cylinder cart Properly secure cylinders Use small quantities or a ventilated gas cabinet Wear safety glasses with side shields while connecting lines Leak check gas lines 		
Solvents	Y	Y	 Limit quantities at beamline to < 250 ml Use PPE - safety glasses, nitrile gloves 		
Pouring cryogens <u><</u> 5L	Y	Y	 Use goggles Long pants and sleeves - avoid clothing which can trap cryogens (pockets, cuffs) Cryogen or heavy gloves Enclosed shoes Never pour from above chest level 		
Using the LN2 Fill Station or pressurized transfer	Y	Y	 LS-PROC-LN2FILL-MANLt raining for fill station Use full face shield along with goggles or safety glasses Long pants and sleeves - avoid clothing which can trap cryogens (pockets, cuffs) Cryogen or heavy gloves Enclosed shoes 		
Cutting/razor blades	Y	Y	 Be aware of hand positioning Use safety knife when possible Consider using cut resistant gloves for frequent cutting tasks 		