Brookhaven National Laboratory – Photon Sciences - National Synchrotron Light Source					
Beamline Hazard Analysis - Beamline X16A					
LS-BHA-X16A	Revision: 02	Effective: 10/17/11	Page 1 of 1		
The following tasks are included in the beamline safety review. Any operations not listed here, or performed by others than					
those listed, need additional review by ES&H personnel and/or beamline personnel.					

Prepared By:	J. Keister	Approved By:	Lori Stiegler

Tasks / Equipment	Performed by:		Controls	
	Beamline	Users		
	Staff			
Solvents	Υ	Υ	<ul> <li>Limit quantities at beamline to &lt; 250 ml</li> </ul>	
			<ul> <li>Use PPE - safety glasses, nitrile gloves</li> </ul>	
Ergonomics concerns –	Υ	Υ	Be aware of body posture,	
moving/lifting			<ul> <li>Ask for help in moving or lifting</li> </ul>	
Ergonomics concerns –	Υ	Υ	<ul> <li>Be aware of body posture</li> </ul>	
awkward postures			Take frequent breaks	
Cutting/razor blades	Υ	Υ	Be aware of hand positioning	
			<ul> <li>Use safety knife when possible</li> </ul>	
			<ul> <li>Consider using cut resistant gloves for frequent</li> </ul>	
			cutting tasks	