

NTSB National Transportation Safety Board

An NTSB Board Member's Perspective

Robert L. Sumwalt

Primary Sources of Data

Major Accidents

Serious Incidents **NTSB**

FOQA, ASAP, LOSA, First Look Data, MV, Line Checks, Special Observations

Airlines

From my perspective...



- Monitoring and Cross-checking
- Sterile Cockpit
 Violations



Monitoring and Cross-Checking



Monitoring and Cross Checking

- Inadequate crew monitoring or challenging was a factor in 31 of 37 (84 percent) crewcaused air carrier accidents reviewed in a NTSB safety study.
 - 76% of the monitoring/challenging errors involved failure to catch something that was causal to the accident
 - 17% of the monitoring/challenging errors were failure to catch something that contributed to the accident's cause



NTSB Finding

 "during the later stages of the approach, the flight crew failed to monitor the airplane's airspeed and allowed it to decrease to a dangerously low level (as low as about 50 knots below the company's recommended approach airspeed) and to remain below the recommended approach airspeed for about 50 seconds."



Accident Summary


- February 16, 2005
- Pueblo, CO
- Cessna Citation 560
 - Owned by Circuit City, Operated by Martinair
- Eight fatalities
- Part 91 flight



Key Findings

- Icing encountered on descent and approach
- Airspeed not maintained on approach
- De-icing boots not operated on approach
- No stall warning before stall





0912:37: I don't know if you want to run your ice a little bit. You got the Vref there.

0912:17: Just a brief on the missed approach, if we have to. It's climb to seven thousand, direct to Pueblo localizer.

All right.

0912:42 Upset

Uh, Pueblo outer marker.

Right turn or left turn.

It doesn't say. It says direct to it, uh ...

All right.

0912:31: Straight ahead on the other side.

Data use subject to license.

www.delorme.com

© 2004 DeLorme. Topo USA® 5.0

I MN (0.0° W) Data Zoom 10-5

Upset Sequence

- Stall occurred at 1500 ft AGL
- Sudden left roll, A/P disconnect
- Airspeed at stall approx. 90 kts

No stall warning before stall due to

ice on wings



Probable Cause

"Flight crew's failure to effectively monitor and maintain airspeed and comply with procedures for deice boot activation on the approach, which caused an aerodynamic stall from which they did not recover."



NTSB Finding

 "All operators would benefit from an increased focus on providing monitoring skills in their training programs..."

NTSB Recommendation to FAA:

Require pilot training programs be modified to contain modules that teach and emphasize monitoring skills and workload management and include opportunities to practice and demonstrate proficiency in these areas.



A good place to start



US Department of Transportation Federal Aviation Administration

Advisory Circular

Subject: STANDARD OPERATING PROCEDURES FOR FLIGHT DECK CREWMEMBERS Date: 2/27/03 Initiated By: AFS-210 AC No: 120-71A

1. PURPOSE.

- a. General. Standard operating procedures (SOPs) are universally recognized as basic to safe aviation operations. Effective crew coordination and crew performance, two central concepts of crew resource management (CRM), depend upon the crew's having a shared mental model of each task. That mental model, in turn, is founded on SOPs. This advisory circular (AC) presents background, basic concepts, and philosophy in respect to SOPs. It emphasizes that SOPs should be clear, comprehensive, and readily available in the manuals used by flight deck crewmembers.
- b. Using this Advisory Circular. This AC is designed to provide advice and recommendations about the development, implementation, and updating of SOPs. Appendix 1, Standard Operating Procedures Template, provides many important topics that should be addressed in SOPs. Stabilized Approach, characterized by a constant-angle, constant-rate of descent ending near the touchdown point where the landing maneuver begins, is among the SOPs specifically identified in this AC and is described in Appendix 2, Stabilized Approach: Concepts and Terms. These and the other appendices represent a baseline and a starting point. Start-up certificate holders and existing certificate holders should refer to the Template in Appendix 1, to Stabilized Approach in Appendix 2, and to the other appendices in developing comprehensive SOPs for use in training programs and in manuals used by their flight deck crewmembers.
- c. What's New in this Advisory Circular. AC 120-71A revises and supersedes the earlier version, AC 120-71. Many minor changes have been made to improve clarity, accuracy, completeness, and consistency. Two significant changes are the conversion of the term pilot not flying (PNF) to pilot monitoring (PM) and the addition of a related Appendix addressing "Crew Monitoring and Cross-Checking." It is increasingly acknowledged that it makes better sense to characterize pilots by what they are doing rather than by what they are not doing. Hence, pilot flying (PF) remains an appropriate term and is unchanged in this AC. But the term pilot not flying misses the point. Studies of crew performance, accident data, and pilots' own experiences all point to the vital role of the non-flying pilot as a monitor. Hence, the term pilot monitoring (PM) is now widely viewed as a better term to describe that pilot. The term PM is used liberally throughout this AC. In those instances where the older term PNF appears, it should be understood that pilot monitoring (PM) is the preferred meaning.

- AC 120-71A,
 "Standard Operating Procedures for Flight Deck Crewmembers"
 - Appendix 19



Sterile Cockpit Violations



Comair Airlines Flight 5191 Lexington, Kentucky

- Bombardier CRJ
- 49 Fatalities
- First officer severely injured
- Wrong runway takeoff





Sterile Cockpit Violation


- 40 of the 150 seconds during taxi were violations of sterile cockpit rule
- Distraction likely contributed to loss of positional awareness



The Probable Cause statement

"Contributing to the accident [was] the flight crew's nonpertinent conversation during taxi, which resulted in a loss of positional awareness ..."







NTSB National Transportation Safety Board

SMS: A Practical Look

Pinnacle Airlines Flight 3701 Jefferson City, Missouri



- October 14, 2004
- Bombardier Regional Jet
- Repositioning flight
- Both flight crewmembers killed



NTSB Conclusion

 "All air carriers would benefit from Safety Management System programs because they would require the carriers to incorporate formal system safety methods into the carriers' internal oversight programs."



NTSB Recommendation to FAA

"Require that all [air carriers] establish Safety Management System programs."

NTSB Recommendation A-07-10



What is a Safety Management System?

"A SMS is an organized approach to managing safety, including the necessary <u>organizational</u> <u>structures</u>, <u>accountabilities</u>, <u>policies</u>, and <u>procedures</u>."

ICAO (Doc 9859 SMM)



When you have SMS, the company ...

- **Systematically** attends to those things it believes are important.
- Manages and values safety, just as they manage and value other vital business functions.
 - Finance: CFO, General Accepted Accounting Practices (GAAP), procedures, controls, audits, accountability



SMS Components

Written policies, procedures and guidelines

2. Data collection and analysis

3. Risk management

4. Safety culture



SMS Components

1. Written policies, procedures, guidelines




Potential Gaps

 The organization does not have adequate written policies, procedures and guidelines.

— or —

They don't rigorously adhere to what they do have.





Inadequate procedures

- Key procedures for briefing and conducting instrument approaches were in "Maneuvers Guide"
 - Pilots were expected to adhere to procedures in "Maneuvers Guide"
 - "Maneuvers Guide" was only issued to the chief pilot and instructors
- Company pilot: never seen any standardized callouts documented in any company manual
 - To compensate, she used callouts she used at another company



Non-Compliance

 Company check airman: rated company's standardization as "6" on a 1 – 10 scale.

- Lead ground instructor: "Fair"
 - Suspected that some pilots were following SOPs while others were not



July 10, 2007, Sanford, FL



 Cessna 310 owned by NASCAR

5 fatalities







Declared Emergency Requested Diversion.

"Smoke in the cockpit."

"Shutting off radios, elec."












Maintenance Discrepancy Entry



Inadequate Procedures

- Maintenance forms not serialized, tracked, or retained
 - Yellow copy never provided
- No procedures for providing flight operations personnel (pilots and dispatchers) with airplane airworthiness information.
- Most often a preflight fact sheet would be taped to airplane with highlighted items signed off by a mechanic
 - Not a requirement, not spelled out in SOP



2. Data collection and analysis



Data leads to informed Risk Management

- "Hazards and incidents resulting from department operations shall be identified at all levels.
- "Conditions and acts posing unacceptable risk shall be eliminated or changed to prevent personal injury or illness and property damage or loss."
 - NBAA Prototypical Safety Manual



3. Risk Management



Risk Management

"We manage risk whenever we modify the way we do something to make our chances of success as great as possible, while making our chances of failure, injury or loss as small as possible."

FAA System Safety Handbook



Step 1: Identify Hazards



HAZARDS

- No precision approach
- No operational tower at night



Approach-and-landing Risk Awareness Tool

Airport Services and Equipment

An port Services and Equipment	
No approach radar service or airport tower service	······································
No current local weather report	
Unfamiliar airport or unfamiliar procedures	
Minimal or no approach lights or runway lights	
No visual approach-slope guidance — e.g., VASI/PAPI	Δ.
Foreign destination — possible communication/language problems	Λ
Expected Approach	
Nonprecision approach — especially with step-down procedure or circling procedure	
Visual approach in darkness	11
Late runway change	ΛΛ
No published STAR	<u> </u>

Step 2: Assess Hazards

PROBABILITY

S **Unlikely** Seldo **Occasional** E V Catastrophic 4 E **Critical** 2 R **Marginal** 2 1 **Negligible**

Hazard

No precision approach No operational tower

RAC

3 (Seldom, Catastrophic)

Likely

4

4

3

3 (Seldom, Catastrophic)

Step 3: Make Risk Decisions & Develop Controls

HAZARDS

- No precision approach
- No operational tower

CONTROLS

We will not use this airport:

between sunset and sunrise when control tower is closed, and
when the weather is forecast below 800/2.



Determining Residual Risk

PROBABILITY

SEVERITY

	Unlikely	Seldom	Occasional	Likely
Catastrophic	2	3	4	4
Critical	1	2	3	4
Marginal	1 /	1	2	3
Negligible	1	1	2	2

Hazard

No precision approach

No operational tower

RAC

1 (Unlikely, Negligible)

1 (Unlikely, Negligible)

4. Safety Culture




Safety Culture

Do employees do the right things, even when no one is watching.



Safety Culture is:



Safety culture starts at the top of the organization and permeates the entire organization.

Written policies, procedures and guidelines

2. Data collection and analysis

3. Risk management

4. Safety culture





NTSB

