

BLDG NO
1854

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2001	4-19-85	638	INSTALL CIRCUIT TO TIG WELDER
2050	11-22-88	990	PROGRAM EXTENT TO INSPECT & CRACK BROW CRANE
2212	4-19-85	1373	INSTALL WIRING & CONNECT TEST BRANCHES 120 VAC & 28 VDC
✓ 3379	11-30-84	2070	REKEY DOOR & EDGE LOCKS INSTALL TIMING CURDS
3968	9-16-86	3185	REMOVE & REPLACE AIR COMPRESSOR
4273	1-18-85	781	REPAIR EXTER. WALL OVER ROLL-UP DOOR
4467	10-26-84	799	REPLACE (2) STEAM HOSE
4011	7-4-86	4400	REPLACE DETERIORATED SHEET METAL BEARING ON WINDOW SILL
4251	9-26-86	3994	REPLACE SHEET METAL BEARING IN COUPLER BALANCE SPRING
4364	Compl	741	REPAIR 6-SECTION OF CURB BEHIND BLDG 1854 7-20-84
4736	Compl	1901	RPA EROSION AREA AROUND COLLECTION PLATINUM FACILITY 8-21-84
✓ 4793	12-21-84	1750	RPA GROUND NOW FREEZE HYDRAULIC AT WASH KAMP
5289		3514	REPLACE DIESEL RE-FUELING PUMP DAMAGED BY TANK
6056	9-25-85	6962	RPL COMPRESSOR IN AIR COND. SYSTEM
4350	5-8-87	5235	REPLACE A/C COMPRESSOR FOR A/C
1028		1396	INST STEAM & WATER BLENDER VALVE
4273	1-18-85	781	RPR EXT WALL OVER ROLL-UP DOOR
2212	4-19-85	1373	INSTALL WIRING & CONNECT TEST BRANCHES 120 VAC + 28 VDC
3046	Compl	12678	REPL PAD-MOUNTED TRANSFORMER
8046	7-29-91	298	HARDEN SECURITY IN TOW WORKS SUPPLY AREA.
1030	4-28-89	4161	CONSTRUCT 2 CASE SYSTEMS
3108	4-8-88	460	RPR HOLE IN EXT WALL OVER ROLL-UP DOOR
3159	2-29-88	827	RPR BLOCK WALL
5289	Compl	3514	RPLC DIESEL RE-FUELING PUMP
3475	2-29-88	718	PROVISE METALL STEAM/WATER BLENDING VALVE

