

| | | | | | |
|-------------------|-----------------------------|---------------------------------------|-----------------------|----------------------|--|
| BLDG NO TC-705 | INT. PAINT SQ FT 7500 sf | EXT. PAINT SQ FT 600 sf 36 windows | ROOF SQ FT 4917 sf | CONDEN. LINES LIN FT | FACILITY HISTORY RECORD MCBCL 11011/3 |
|-------------------|-----------------------------|---------------------------------------|-----------------------|----------------------|--|

| JOB ORDER NO or Contract No. | DATE COMPLETED | COST | DESCRIPTION |
|---------------------------------|-------------------|--------|---|
| | | | |
| | | | |
| Contract | 3/11/71 | | Reroofing |
| 4579 | 6-29-73 | 828 | misc rep to bldg. |
| 8472 | | 2684 | install telephone key sept. |
| 1169 | 3-29-73 | 3774 | construct ofc spaces |
| 1064 | 11-16-73 | 647 | increase size in bldg |
| 14595 | 6-29-73 | 2020 | rep & paint int |
| 3432 | 8-29-75 | 13641 | Remove steam & Condensate lines |
| 3869 | 11-14-75 | 811 | Repair duct in TC-709 & Insulate pipe |
| 2684 | 1-15-74 | 420 | Remove class. 250' pole |
| Contract # 79-2615 | Fy 79 | 2000 | Ext. + Int. paint |
| 3611 | 2-29-80 | 538 | Rpl. tube bundle in hot water heater |
| 3084 | 2-8-80 | 483 | Rpl. steam coil in heating unit |
| 3332 | 11-20-80 | 696 | Rpl. steam coil |
| 3706 | 5-23-80 | 334 | Rpr to roof framing & metal roofing |
| 3706 | 5-23-80 | 1,532 | Rpl. roof framing & metal roofing |
| 3881 | Comp | 6479 | Replace window screens & screen door |
| 4295 | 11-20-81 | 303 | Repair to bldg before contract painting |
| 4148 | 9-23-83 | 1344 | Interior Repairs |
| 4767 | 12-18-84 | 458 | Maint Issue material for self Helys project |
| C008 | 9-12-85 | 1720 | MISC. Struct., Elect. & Mech Repairs |
| 3717 | 3-2-84 | 13,508 | Replace Exterior Walk-way Lights |
| | | | |
| | | | |

