

BLDG NO
M-424

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

| JOB ORDER NO or Contract No. | DATE COMPLETED Signed | COST | DESCRIPTION |
|---------------------------------|-----------------------------|-------------------------------|---|
| 044-070-076 | 7/3/61 | 1,006.40 | Four concrete slab for dumpster and prep drainage ditch (C 7/28/61) |
| 023-02371-82 | 7/12/62 | E 1158 | Paint exterior |
| 023-02943-82 | 12/20 /63 | E 2112 | Renovate exterior |
| 023-08151 | 3/25/63 | E 664 | Repair roof |
| NB4-04372-22 | 7/1/63 | 1544.92 1544.92 | Renovate return lines |
| NB4-04720-22 | 10/23/63 | 821.96 821.96 | Repairs and paint |
| NB4-03649-22 | 11/27/63 | 1139.13 1139.13 | Install new dishwasher |
| CONTRACT | C 8/13/64 | | Waterproofed |
| " | 4/8/70 - Completed | | Interior repairs & paint / exterior repairs & paint |
| 3642 | 8-16-74 | 514 | Replace A.C. Compressor |
| N62470-71-C-0536 | 3/19/72 | | Install garbage disposal equipment |
| 2642 | 4-27-73 | 826 | Hook up water/elect to (6) auto coffee makers |
| 2723 | 6-8-73 | 644 | Repair insinger dishwashing machine |
| 4043 | 11-10-72 | 2088 | Repair deck under copper |
| 4283 | 1-5-73 | 63 | Replace 60amp 3ph safety switch |
| 3353 | 10-2-73 | 947 | Replace 4" water main & valve |
| 2377 | 3-15-74 | 500 | PM follow up to galley equip |
| 2448 | 9-21-73 | 366 | Replace dishwashers in NCB area |
| 2334 | 2-22-74 | 742 | Repair gas Range |
| 2612 | 6-21-74 | 150 | Install gas grills |
| 2853 | 9-24-76 | 320 | Provide 60AMP for portable refrigeration |
| 2484 | | 1253 | Install one 2 other gas connection over |
| 2763 | 4-25-75 | 64 | Replace grease filter |
| 2670 | 2-7-75 | 1093 2155 | Hook up water & drain to steam tables |
| 4576 | 4-4-75 | 381 | Install casters on bussing carts |
| 2773 | 6-13-75 | 910 | Install 2 Circuits for milk shake machine |
| 2418 | | 1070 | Relocate (2) Noods, steam tables & grills |

| JOB ORDER NO | DATE COMPLETED | COST | DESCRIPTION |
|--------------|----------------|--------|---|
| 4208 | Comp | 258 | Repairs to Vegetable reefers |
| 5311 | 12-8-78 | 915 | Cover interior of meat reefers w/ aluminum bolt through ceiling, cables |
| 3978 | 3-3-78 | 838 | Remove linoleum and adhesive backing from mess deck |
| 3867 | 2-10-78 | 309 | Remove fallen tree and debris Build-up seat 1/3 round at outfalls |
| 2469 | 3-9-79 | 448 | Disconnect old stack oven install new 3 stack oven in galley |
| 3541 | 10-12-79 | 1817 | Cover ceiling in Prodn/dairy reefers w/ Al Canek around edge |
| 5311 | Comp | 915 | Cover interior meat reef with alumin Canek around edge |
| D.C. 2059 | 8-15-81 | 21,160 | Installation of freezer & cooler boxes |
| 3052 | 9-26-79 | 814 | Replc. Exhaust fan |
| 2488 | 2-9-79 | 248 | Replc wood supports underneath |
| 4395 | 10-3-79 | 13,448 | EXT Repair wnt & ext part |
| 4161 | 9-26-80 | 690 | Rpl window balances |
| 4273 | 8-22-80 | 489 | Rpl. (90) window screens |
| 2020 | 11-21-80 | 2033 | Install (2) reg. steam cookers & arch. steam kettle high |
| 2086 | Comp | 1596 | Install equip & associated utilities |
| 4130 | 10-31-80 | 19859 | Int. rpl & paint (2) coats |
| 2018 | 12-19-80 | 192 | Install new circuits for galley equip |
| 2004 | 2-27-81 | 185 | Construct & paint steel angle frame. |
| 3230 | 11-14-80 | 143 | Rpl. (1) tank type commode |
| 2122 | Comp | 467 | INSTALL (2) 30 AMP 120/208 3Ph receptacles |
| 1385 | Comp | 6224 | Relocate (2) 600 cu FT Refers 15 feet |
| 1385 | 11-24-82 | 5073 | Seahut |
| 1385 | 6-28-82 | 22,734 | Seahut |
| 1385 | Comp | 115 | Seahut |
| 1385 | Comp | 444 | Strong Back tent |
| 1385 | Comp | 2403 | Salad room shelter |
| 1385 | 10-1-82 | 716 | Seahut Walkway |