

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

TT-43

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
6619	3-28-75	1699	Replace water cooled towers w/air cooled ^{condemning unit}
60315	4-1-74	415	(3) Pigeon hole deck tops
7756	4-23-73	2234	Repair & paint int
7744	4-24-73	856	Repair & paint ext
8108	6-13-72	1175	Replace flo lights throughout Bldg
7747	3-31-72	79	Repaint signs
9100	1-8-71	700	Install exit door unit on rear 3 Bldg
60866	10-9-70	705	Replace heating coil
31799	3-3-69	119	Repair ceiling & floor tile
7895	6-27-75	289	Install red wood fence
6631	9/22/77	939	Cut grass weekly
6645	9/30/77	876	Cut grass weekly.
6658	10/2/78	1,027	cut grass weekly.
8827	7/8/74	330	cut grass weekly.
3496	77	724	Install valve on by pass sewer line at sewerage lift stat.
6029	3-14-86	3959	LANDSCAPE LAWN. SH 2-5
6503	2-14-86	5146	Rem. walls, PATCH FLOOR TILES: Install I Beam post prior to CONTRACTOR installing ceiling. RENOVATE INTERIOR.
6501	8-28-88 10/3/97	6308	INSTALL Generator

