

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4019	5-9-75	618	Install valve on the condenser line to A/C
3446	8-8-75	543	Replace metal door jamb & secure to block wall
3743	2-23-78	2520	Self-help paint
4022	5-3-77	690	Paint int. (3 rooms)
Cont# 78-3029	Fy P	1657	Ext. paint
4755	12-1-78	1023	Rpl. rusted out door and exhaust fan
2642	6-2-78	329	Install washer and dryer 2d deck laundry room
3056	8-14-81	3138	Int. rprs
4364	8-14-81	728	Rpl. rusted out door frame
3763	8-7-81	389	Replace tube bundle
1102	8-14-81	211	Replace door closer & adjust door
4460	4-2-82	4,317	Repair int. Doors, floor tiles, ceiling tiles,
3173	4-1-82	6,774	Rpl. missing screens
3897	11-26-82	731	Install V-Blinds
4818	Comp	9542	Int. rpr.
3421	Comp.	977	Misc. lighting rpr.
4674	Comp	1700	Replace V-Blinds
5071	2-24-84	547	Replace missing window screens
3219		16,735	Relight Bldg
5238	5-9-84	1097	Repair busted water main
4579	8-9-84	3956	Repl Waste & Vent (Sewer) Piping
3219	9-18-87	16735	Relight Bldg
3195	4-4-86	2301	Replace Venetian Blinds
4208	4-19-85	2617	Paint Ext Trim
5184	4-16-85	4044	Perform cyclic Paint Repairs
5229	4-5-85	430	Spotite Interior Paint

