

JANUARY			FEBRUARY			MARCH			APRIL			MAY			JUNE			REMARKS	
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.		DRAW DOWN
TC 100		NO AIR LINE																	
201	38'	30'	8'	38'			52'	7'	45'	20'	19'	1'	51'	30'	21'	14'	22'	8'	
502				35'	20'	15'	38'			30'	22'	8'	37'	31'	6'	26'	32'	6'	
504	70'	12'	58'	70'	14'	56'	40'	15'	25'	38'	10'	28'	40'	13'	27'				
600	36'	22'	14'	38'	26'	12'	37'	31'	6'	37'	14'	23'	36'	30'	6'	25'	33'	8'	
604																10'	39'	29'	
700	38'	15'	23'	40'			41'	20'	21'	40'	5'	35'	39'	13'	26'	13'	43'	30'	
901	44'	32'	12'	36'			38'			38'	29'	9'	18'	31'	13'	23'			
1000		Down			Down														
1001	42'	26'	16'					33'		44'	25'	19'	35'	22'	13'	40'	28'	12'	
MCAS 126		40'		60'	51'	9'	61'	53'	8'	63'	53'	10'		52'		58'	51'	7'	
131																			

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

0000003597

CLW

						WELL			PU											
JANUARY			FEBRUARY			MARCH			APRIL			MAY			JUNE					
1979																				
MCAS-110																				
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS	
MCAS 161	20'	54'	34'	26'	65'	39'	19'	60'	41'	18'	58'	40'	19'	53'	34'	35'	55'	20'		
163	10'	37'	27'		17'			38'		10'	39'	29'				10'	37'	27'		
169	24'	28'	4'	27'	30'	3'	23'	30'	7'	22'	28'	6'	23'	28'	5'	24'	28'	4'		
165	33'			32'						32'			9'	39'	30'					
164	30'	25'	5'	21'	24'	3'	21'	24'	3'	20'	23'	3'	20'	22'	2'	20'	32'	12'		
203																			NO FITTING GAUGE	
3506																				
4140							94'	90'	4'	96'										
4150	60'						82'	80'	2'	86'	78'	8'	89'			30'	40'	10'		
5001																			1 1/2 LINE STOPPED 4	
5009							68'	52'	18'	72'	26'	46'				68'	22'	46'		
70 202	60'	32'	28'	62'	32'	30'	62'	36'	26'	61'	38'	23'								

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

0000003598

CLW

WELL 1

JULY

AUGUST

SEPTEMBER

OCTOBER

NOVEMBER

DECEMBER

1979
MCAS-110

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
TC 100	NO AIR LINE																		
201	10'	30'	20'	11'	28'	17'	9'	30'	21'	8'							9'	26'	17'
502	25'	31'	6'	26'	33'	7'	26'	31'	5'	30'							29'	35'	6'
504																			
600	26'	33'	7'	25'	32'	7'	24'	27'	3'		29'						25'	29'	4'
604	14'	38'	24'	13'	38'	25'	12'	30'	18'		32'						10'	33'	23'
700	14'	35'	21'	14'	38'	24'	13'	41'	28'	15'							17'	29'	12'
901	25'	23'	2	24'	27'	3'	23'	26'	3'		23'						26'	23'	3'
1000																			
1001 MCAS	38'	22'	16'	38'	24'	14'	46'	26'	20'		26'						27'	22'	5'
106				60'	51'	9'	18'	24'	6'								37'	23'	14'
131																	CLW		

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

000003599

JULY 1979 MCAS-110			AUGUST			SEPTEMBER			OCTOBER			NOVEMBER			DECEMBER			REMARKS	
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.		DRAW DOWN
^N 1256 161	20'	54'	34'	24'	52'	28'	20'	48'	28'	25'	46'	21'				22'	46'	24'	
^N 1255 163	10'	32'	22'	8'	34'	26'	12'	36'	24'	10'	35'	25'				13'	33'	20'	
^D 1254 164	26'	28'	2'	24'	29'	5'	28'	28'	0'	25'	28'	3'				26'	23'	3'	
^N 1253 165	31'			33'	43'	10'	33'	35'	2'	34'	30'	4'				33'	37'	4'	
^R 1251 166	20'	24'	4'	20'	26'	6'	22'	25'	3'	20'	23'	3'				21'	25'	4'	
209																			
3506																			
4140				33'	35'	2'	31'	36'	5'	32'	33'	1'				28'	33'	5'	
4150				31'	35'	4'	26'									53			
5001				30'	55'	25'	32'	55'	23'										
5008				23'	53'	30'	?	?											
TC 202																			

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

000003600

CLW