

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 15

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 15

Facility Name: Surry 2 Docket (050- 00281)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00281/2006-009
111 - Procedure / reference document technical content	I - Instrumentation & Control	G - Design	050-00281/2006-006
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00281/2006-002
Number of Items for this Docket: 3			
Percent of Total for this Docket: 20			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00281/2006-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00281/2006-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 13			
Training / IR			
101 - Training process problem	D - Emergency Planning	D - Emergency Drill	050-00281/2006-008
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00281/2006-009
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00281/2006-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00281/2006-004
187 - Action implementation LTA	I - Instrumentation & Control	G - Design	050-00281/2006-006
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00281/2005-005
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	D - Emergency Drill	050-00281/2006-008
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00281/2006-009
197 - Self-check LTA	O - Operations	B - Bal of Plant Ops	050-00281/2005-005
Number of Items for this Docket: 8			
Percent of Total for this Docket: 53			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00281/2006-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 7			
Total Items for this Docket: 15			
